
Profile/Ph	oto Observatio	n Report				RedZon R 0 B 0 T I C S
Date:	04/04/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	): <b>175.1</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	)	PSR:	P-708-107-106
Customer:		Clean Date	: 01/01/1900		Shape:	C
Street:	BRACKEN PKWY & TAMARACK DR		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewe	d:		
Location:	Sidewalk		Tape/Media	#:		
Purpose:	Maintenance Rela	ated	Dia/Height:		12"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:						
Location Detail	S:		Direction of S	urvey:	Upstream	
US MH:	M-708-107	DS MH:	M-708-106	Тс	otal Length Surveyed (ft)	: <b>185.7</b>
0&M Index:	0.00	O&M Quick	: (	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural C	luick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-106



Code: Description:

Water Level

MWL

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



AMH		
Manhole		
185.7		
0		
0		
NO		
M-708-107		