
Date:	04/03/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)		Owner:	NA		-	Not Known
P.O.#:		Surveyor:	Jen Costello			P-708-110-109
Customer:		Clean Date:			-	C
Street:	BRACKEN PKWY		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Sidewalk		Tape/Media #:			
Purpose:	Maintenance Relat	ed	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:						
Location Detail	s:		Direction of Sur	vey:	Downstream	
US MH:	M-708-110	DS MH:	M-708-109	Total Leng	th Surveyed (ft):	10.9
O&M Index:	2.00	O&M Quick:	220	0 0 O(&M Rating:	4.00
Structural Index:	0.00	Structural Qu		00 Sti	ructural Rating:	0.00
Overall Index:	2.00	Overall Quic		00 0.	verall Rating:	4.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-110



Code: Description:

Within 8" of Joint:

Remarks:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index:

MWL


Water Level



Code:	DAGS
Description:	Deposits Attached Grease


NO

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



Code:MSADescription:Abandoned Survey

Distance (ft):	10.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	overturned



Code:
Description:

DAGS Deposits Attached Grease

Distance (ft):	10.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	