

Profile/Ph	oto Observatio	n Report			RedZo
Date:	04/02/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): 281.4	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-708-123-122
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Redbud		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Sidewalk		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	e
Category:	NA				
Comment:	Flow direction wr	ong.			
Location Detai	ls:		Direction of Sur	vey: Upstream	
US MH:	M-708-122	DS MH:	M-708-123	Total Length Surveyed (f	it): 290.8
D&M Index:	2.00	O&M Quick:	220	00 O&M Rating:	4.00
Structural Index:	0.00	Structural Q	uick: 000	00 Structural Rating	g: 0.00
Overall Index:	2.00	Overall Quic			4.00

	Position	Code	Observation	Video (sec)	Grade
M-708	-123				
	.0	AMH	Manhole	10	NA
- H	-///.0	MWL	Water Level	21	NA
- 11	12.2	TF	Tap Factory	57	NA
- 11	15.7	TF	Tap Factory	77	NA
- 11	86.2	TF	Tap Factory	230	NA
- 11	/142.4	TF	Tap Factory	355	NA
- 11	/ 142.4	DAGS	Deposits Attached Grease	367	M 2
- 11	/ 170.7	TF	Tap Factory	435	NA
- 11	199.0	DAGS	Deposits Attached Grease	504	M 2
5	199.3	TF	Tap Factory	516	NA
Camera Direction	228.4	TF	Tap Factory	587	NA
Di Di	267.7	TF	Tap Factory	679	NA
nera	271.0	TF	Tap Factory	702	NA
Car	290.8	AMH	Manhole	755	NA
M 709					
M (708	-122				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-123




Code: MWL Description: Water Level


Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	12.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	15.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TF
Description:	Tap Factory
Distance (ft):	86.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To: 1st Value: 2nd Value: Value Percent:	4.000
Continuous Index: Within 8" of Joint: Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	142.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	142.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code:	TF
Description:	Tap Factory

170.7
0
0
12
4.000




Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	199.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	199.3
	199.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	

Continuous Index: Within 8" of Joint: Remarks:




Code:	TF
Description:	Tap Factory
Distance (ft):	228.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	4.000
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	267.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value:	271.0 0 0 12 4.000
2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	



Code:AMHDescription:Manhole

Distance (ft):	290.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-122