
Profile/Ph	oto Observation	Report				RedZone
Date:	10/12/2018	Weather:		Co	oding: F	PACP 6.0
Pipe Length (ft): 80.1	Owner:	NA	Pr	e Clean: 🛛 🛚	Not Known
P.O.#:		Surveyor:	Selasie Honu	PS	SR: F	P-708-128-127
Customer:		Clean Date:	01/01/1900	Sh	nape: (C
Street:	Magnolia Dr.		Flow Control:	No	ot Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Light Highway		Tape/Media #:			
Purpose:	Routine Assessmen	t	Dia/Height:	8"		
Use:	Sanitary		Material:	PV	'C	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction of Sur	vey: Up	ostream	
US MH:	M-708-127	DS MH:	M-708-128	Total Length	Surveyed (ft):	83.1
0&M Index:	0.00	O&M Quick:	00	00 O&M	I Rating:	0.00
tructural Index:	0.00	 Structural Qu	ick: 000	00 Struc	tural Rating:	0.00
Overall Index:	0.00	Overall Quick	. 000	00 Overa	all Rating:	0.00






Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-128



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	20.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	50.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



TF Tap Factory
52.4
0
0
3
4.000



Code:	AMH
Description:	Manhole

Distance (ft):	83.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-127