
Profile/Ph	ioto Observatio	n Report			RedZor
Date:	03/30/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): 245.4	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-708-152-151
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Lake		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Sidewalk		Tape/Media #:		
Purpose:	Maintenance Rel	lated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	Flow direction w	rong.			
Location Detai	ls:		Direction of Surv	vey: Downstream	
US MH:	M-708-151	DS MH:	M-708-152	Total Length Surveyed (ft)	: 264.2
D&M Index:	3.00	O&M Quick:	310	00 O&M Rating:	3.00
Structural Index	0.00	Structural Qu	uick: 000	00 Structural Rating:	0.00
Overall Index:	3.00	Overall Quic	k. 310		3.00

	Position	Code	Observation	Video (sec)	Grade
M.708-	151				
\square	0. /	AMH	Manhole	10	NA
- 11	\\0	MWL	Water Level	21	NA
- 11	10.5	TFA	Tap Factory Active	55	NA
- 11	57.8	TF	Tap Factory	163	NA
- 11	165.6	TFA	Tap Factory Active	393	NA
	180.8	TFA	Tap Factory Active	436	NA
	244.4	TF	Tap Factory	576	NA
	246.1	TFA	Tap Factory Active	592	NA
	249.0	TFA	Tap Factory Active	610	NA
5	256.6	MWL	Water Level	638	NA
ecti	261.4	DSF	Deposits Settled Fine	659	M 3
	264.2	AMH	Manhole	676	NA
Camera Direction					
M(708)	152				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-151



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	10.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3

4.000

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:




Code:	TF
Description:	Tap Factory

Distance (ft):	57.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TFA
Description:	Tap Factory Active
Distance (ft):	165.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description: TFA Tap Factory Active

Distance (ft):	180.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	244.4 0 0 3 4.000
Within 8" of Joint: Remarks:	



Code: Description: TFA Tap Factory Active

Distance (ft):	246.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Remarks:




Code:	TFA
Description:	Tap Factory Active
Distance (ft):	249.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	



Code: MWL Description: Water Level

Distance (ft):	256.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSF
Description:	Deposits Settled Fine

Distance (ft):	261.4
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: AMH Description: Manhole

264.2
0
0
NO
M-708-152