Profile/Ph	oto Observation	n Report				RedZon
Date:	04/06/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 399.0	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Coste	llo	PSR:	P-708-019-021
Customer:		Clean Date	e: 01/01/19	00	Shape:	с
Street:	OFF S LAKE PARK AVE		Flow Contr	ol:	Not Controlled	
City:	Hobart, IN		Year Renev	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Maintenance Rela	ated	Dia/Height	:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:						
Location Detail	ls:		Direction o	f Survey:	Downstream	
US MH:	M-708-198	DS MH:	M-708-021	Тс	otal Length Surveyed (ft):	399.6
0&M Index:	0.00	O&M Quick		0000	O&M Rating:	0.00
Structural Index:	0.00	Structural C	Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade
M(708-)1	98				
	.0	AMH	Manhole	10	NA
	\ <u>.</u> 0	MWL	Water Level	21	NA
	43.7	TF	Tap Factory	120	NA
_	104.1	TF	Tap Factory	253	NA
_	/126.7	MGO	General Observation	312	NA
	/154.8	TF	Tap Factory	380	NA
	//184.4	TF	Tap Factory	451	NA
	223.9	TF	Tap Factory	542	NA
	294.1	TF	Tap Factory	695	NA
5 – /	346.6	TF	Tap Factory	812	NA
e cri	399.6	AMH	Manhole	932	NA
Camera Direction					
M-708-0	21				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-198



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	TF Tap Factory	
Distance (ft):	43.7	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:	11	
Clock To:		
1st Value:	4.000	
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:		
Remarks:		



Code:	TF
Description:	Tap Factory

104.1
0
0
10
4.000



Code:	MGO
Description:	General Observation

Distance (ft):	126.7	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	rear camera	




Code:	TF
Description:	Tap Factory

Distance (ft):	154.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	184.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	223.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	294.1 0 0 11 4.000
Within 8" of Joint: Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	346.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	399.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-021