

Profile/Photo Observation Report							
Date:	04/01/2018	Weather:		Coding:	PACP 6.0		
Pipe Length (f	t): 301.7	Owner:	NA	Pre Clean:	Not Known		
P.O.#:		Surveyor:	Jen Costello	PSR:	P-808-001-202		
Customer:		Clean Date:	01/01/1900	Shape:	с		
Street:	Capitol		Flow Control:	Not Controlled	l		
City:	Hobart, IN		Year Renewed:				
Location:	Sidewalk		Tape/Media #:				
Purpose:	Maintenance Rel	ated	Dia/Height:	12"			
Use:	Sanitary		Material:	PVC			
Drain Area:	NA		Lining:	Cured in Place			
Category:	NA						
Comment:	Flow direction w	rong.					
Location Detai	ils:		Direction of Surv	vey: Downstream			
US MH:	M-708-202	DS MH:	M-808-001	Total Length Surveyed (ft)): 296.3		
D&M Index:	0.00	O&M Quick:	000	00 O&M Rating:	0.00		
Structural Index	. 0.00	Structural Q	uick: 000	00 Structural Rating:	0.00		
Overall Index:	0.00	Overall Quic			0.00		






Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-202



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 10.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	AMH Manhole
Distance (ft):	296.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-808-001

Tuesday, December 8, 2020