

| Profile/Photo Observation Report | | | | | | | |
|----------------------------------|----------------------------|---------------------------------|---------------------------|-------------------------------|--|--|--|
| Date: Pipe Length (ft | 10/20/2021 t): 921_1 | Weather: Owner: Surveyor: | Hobart, IN M. Pielacha | Coding: Pre Clean: PSR: | PACP 6.0 Not Known P-709-002-003 | | |
| Customer: | Hobart, IN | Clean Date: | | Shape: | С | | |
| Street: Bracken Parkway | | | Flow Control: | | | | |
| City: Hobart, IN | | | Year Renewed: | | | | |
| Location: Sidewalk | | | Tape/Media #: | 921 | | | |
| Purpose: Routine Assessment | | t | Dia/Height: | | | | |
| Use: | Sanitary | | Material: | PVC | | | |
| Drain Area: | | | Lining: | | | | |
| Category: | NA | | | | | | |
| Comment: | | | | | | | |
| Location Details: | | | Direction of Surve | ey: Downstream | | | |
| US MH: | M-709-2 | DS MH: | M-709-3 | Total Length Surveyed (ft |): 169.0 | | |
| 0.00 O&M Index: | | O&M Quick: | 0000 | O&M Rating: | 0.00 | | |
| Structural Index | . 0.00 | — Structural Qu | ick: 000 0 | Structural Rating: | 0.00 | | |
| Overall Index: | 0.00 | — Overall Quick | .: 0000 | Overall Rating: | 0.00 | | |

Thursday, May 4, 2023 1

| | Position | Code | Observation | Video (sec) | Grade |
|------------------|----------|------|-------------|-------------|-------|
| V 1-709-2 | 2 | | | | |
| | .0 | AMH | Manhole | 0 | NA |
| | 0. | MWL | Water Level | 12 | NA |
| ш | 36.1 | TF | Tap Factory | 60 | NA |
| ш. | 71.3 | TF | Tap Factory | 109 | NA |
| | 121.2 | TF | Tap Factory | 178 | NA |
| | 169.0 | AMH | Manhole | 243 | NA |
| | | | | | |

Code:



| Description: | Manhole |
|--|---------------|
| Distance (ft): Structural Grade: | .0 0 |
| O&M Grade: Clock Start/From: | 0 |
| Clock To: 1st Value: | |
| 2nd Value: Value Percent: | |
| Continuous Index: Within 8" of Joint: Remarks: | NO M-709-2 |

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

IIL.



Code: TF
Description: Tap Factory

Distance (ft): 36.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:


1st Value: **4.000**

NO

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 71.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 121.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 169.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-709-3