
Profile/Ph	noto Observatio	n Report				RedZon
Date:	03/20/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	t): 201.0	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	John Kugl	maier	PSR:	P-709-005-006
Customer:		Clean Date	: 01/01/190	00	Shape:	с
Street:	Oak		Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Yard		Tape/Media	a #:		
Purpose:	Maintenance Rela	ated	Dia/Height:		10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ils:		Direction of	[:] Survey:	Upstream	
US MH:	M-709-005	DS MH:	M-709-006	Тс	otal Length Surveyed (ft):	192.7
)&M Index:	0.00	O&M Quick	:	0000	O&M Rating:	0.00
tructural Index	. 0.00	Structural Q	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quid	·k·	0000	Overall Rating:	0.00





Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-006



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	35.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	77.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: MWL Description: Water Level

Distance (ft):	162.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	50.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	192.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-005