Profile/Photo Observation Report



 Date:
 03/21/2018
 Weather:
 Coding:
 PACP 6.0

 Pipe Length (ft):
 92.6
 Owner:
 NA
 Pre Clean:
 Not Known

 P.O.#:
 Surveyor:
 Selasie Honu
 PSR:
 P-709-010-0

P.O.#: Surveyor: **Selasie Honu** PSR: **P-709-010-005**Customer: **Clean Date: 01/01/1900** Shape: **C**

Street: DUNLIN CT & BRACKEN PKWY Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA
Comment: Mh confirmed, heavy silt in D/S bell.

Location Details: Direction of Survey: **Downstream**

US MH: **M-709-005** DS MH: **M-709-010** Total Length Surveyed (ft): **90.9**

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
709-005				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
14.0	MWL	Water Level	60	NA
90.9	AMH	Manhole	225	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:	NO	
Within 8" of Joint: Remarks:	NO M-709-005	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value:

2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: MWL Description: **Water Level**

Distance (ft): 14.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 90.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: M-709-010

NO