Profile/Photo Observation Report



Date: 03/31/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 299.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-709-007-008

Customer: 01/01/1900 Clean Date: Shape:

Bracken Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Tape/Media #: Location: **Light Highway**

Purpose: **Maintenance Related** Dia/Height: 8" **PVC** Use: Sanitary Material:

NA Lining: **Cured in Place** Drain Area:

NA Category:

Comment:


Location Details: Direction of Survey: **Downstream**

US MH: M-709-007 M-709-008 Total Length Surveyed (ft): DS MH: 294.5

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:


(709) 007				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
281.7	MWL	Water Level	596	NA
294.5	AMH	Manhole	633	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-007

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

40.000

NO


Remarks:

Code:

MWL

Description:

Water Level



Distance (ft): 281.7 Structural Grade: 0

O&M Grade: 0


Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 294.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-709-008