Profile/Photo Observation Report



Date: 03/19/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 80.9 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **John Kuglmaier** PSR: **P-709-011-010**

01/01/1900

Shape:

Street: **DUNLIN CT** Flow Control: **Not Controlled**

Clean Date:

City: Hobart, IN Year Renewed:

Location: Yard Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA
Comment: full of heavy blk silt at 9'.

Customer:

Location Details: Direction of Survey: **Downstream**

US MH: **M-709-010** DS MH: **M-709-011** Total Length Surveyed (ft): **10.1**

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Pos	sition Code	Observation	Video (sec)	Grade
709-010				
0.	АМН	Manhole	10	NA
0.	MWL	Water Level	21	NA
10.1	1 MWL	Water Level	53	NA
10.1	1 MSA	Abandoned Survey	64	NA
ш				
ш				

Code:



Manhole	
.0	
0	
0	
NO	
M-709-010	

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 30.0

Continuous Index:

Within 8" of Joint:

Remarks:

30.000

NO



Code: MWL

Description: Water Level

Distance (ft): 10.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 50.000

 $Continuous\ Index:$

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 10.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: Unknown