
Profile/Photo Observation Report						
Date: Pipe Length (ft) P.O.#: Customer:	03/19/2018 ): 200.1	Weather: Owner: Surveyor: Clean Date:	NA Byrd Fitzgeral 01/01/1900		Clean: Not Kr P-709-	
Street:	DUNLIN CT & WA	XWING CIR	Flow Control:	Not 0	Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Yard		Tape/Media #:			
Purpose:	Maintenance Rela	ated	Dia/Height:	8"		
Use:	Sanitary		Material:	PVC		
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	s:		Direction of Sur	rvey: Dow	nstream	
US MH:	M-709-014	DS MH:	M-709-015	Total Length Su	rveyed (ft): 21	15.0
D&M Index:	0.00	O&M Quick:	00	00 O&M Ra	ating:	0.00
Structural Index:	0.00	Structural Q	uick: 00	00 Structur	al Rating:	0.00
Overall Index:	0.00	Overall Quic	k: 00	00 Overall	Rating:	0.00





Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-014



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	TF Tap Factory
Distance (ft):	52.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	187.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	215.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-015