Profile/Ph	oto Observatio	n Report				RedZone
Date:	03/19/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 153.1	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	John Kugl	maier	PSR:	P-709-028-029
Customer:		Clean Date	: 01/01/19	00	Shape:	с
Street:	Oak		Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Yard		Tape/Medi	a #:		
Purpose:	Maintenance Rela	ated	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction o	f Survey:	Downstream	
US MH:	M-709-029	DS MH:	M-709-028	То	otal Length Surveyed (ft)	151.7
0&M Index:	2.00	O&M Quick	:	2100	O&M Rating:	2.00
itructural Index:	0.00	Structural C	uick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quid	ck:	2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
N(709-)	029				
	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	11.5	MWL	Water Level	56	NA
	50.0	TF	Tap Factory	144	NA
	50.5	DAGS	Deposits Attached Grease	157	M 2
	98.2	MWL	Water Level	264	NA
	99.5	TF	Tap Factory	278	NA
	151.7	AMH	Manhole	394	NA
Lamera Direction					



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-029

_



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MWL Water Level
Distance (ft):	11.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	25.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	50.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease
Distance (ft):	50 5

Distance (ft):	50.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: MWL Description: Water Level

Distance (ft):	98.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Distance (ft): 99.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2 Clock To: 2 1st Value: 4.000 2nd Value: 4.000 Value Percent: Continuous Index: 4 Within 8" of Joint: 4	Code: Description:	TF Tap Factory
O&M Grade:OClock Start/From:2Clock To:11st Value:4.0002nd Value:Value Percent:Continuous Index:1	Distance (ft):	99.5
Clock Start/From: 2 Clock To: 1st Value: 4.000 2nd Value: Value Percent: Continuous Index:	Structural Grade:	0
Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	O&M Grade:	0
1st Value:4.0002nd Value:Value Percent:Continuous Index:	Clock Start/From:	2
2nd Value: Value Percent: Continuous Index:	Clock To:	
Value Percent: Continuous Index:	1st Value:	4.000
Continuous Index:	2nd Value:	
	Value Percent:	
Within 8" of loint:	Continuous Index:	
	Within 8" of Joint:	
Remarks:	Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	151.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-709-028