Profile/Photo Observation Report

P.O.#:



P-709-036-007

Date: 03/19/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 350.1 Owner: NA Pre Clean: Not Known

John Kuglmaier

PSR:

Customer: Clean Date: 01/01/1900 Shape: C

Street: MERGANSER ST Flow Control: Not Controlled

Surveyor:

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA
Comment: 2nd attempt. unknown rollover at 32'.

Location Details: Direction of Survey: **Downstream**

US MH: M-709-036 DS MH: M-709-007 Total Length Surveyed (ft): 33.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Code	Observation	Video (sec)	Grade
09-036				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
4.6	TF	Tap Factory	42	NA
7.9	MWL	Water Level	61	NA
33.4	MSA	Abandoned Survey	123	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-709-036		

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code:

TF

Description: **Tap Factory**



Distance (ft): 4.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 1

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 7.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 33.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: Unknown