Profile/Photo Observation Report



Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 301.4 Owner: NA Pre Clean: **Not Known** P.O.#: John Kuglmaier PSR: P-802-005-006 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Hobart Rd Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Main Highway - Suburban/Rural Tape/Media #:

Purpose: Resurvey Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA


Comment:

Location Details: Direction of Survey: Upstream

US MH: M-802-006 DS MH: M-802-005 Total Length Surveyed (ft): 293.0

1.98 2111 103.00 O&M Index: O&M Quick: O&M Rating: 5.00 5100 5.00 Structural Quick: Structural Rating: Structural Index: 2.04 **512**I 108.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
802	005				
	0.	AMH	Manhole	10	NA
Н	¬∭ <u>.0</u>	MWL	Water Level	21	NA
Н	¬\\\\\.0	DAZ(S01)	Deposits Attached Other	33	M 2
	2.5	HSV	Hole Soil Visible	49	S 5
	2.5	DAE	Deposits Attached Encrustation	61	M 2
	16.5	RFJ	Roots Fine Joint	101	M 1
ш	29.3	TF	Tap Factory	138	NA
Н	35.7	DAZ(F01)	Deposits Attached Other	163	M 2
ш	35.7	DAGS(S02)	Deposits Attached Grease	174	M 2
ш	51.5	MWL	Water Level	217	NA
П	55.5	DAGS(F02)	Deposits Attached Grease	236	M 2
ш	65.8	DAGS(S03)	Deposits Attached Grease	268	M 2
ш	89.9	DAGS(F03)	Deposits Attached Grease	328	M 2
Ш	89.9	DSF(S04)	Deposits Settled Fine	339	M 2
ш	120.7	TBI	Tap Break-in Intruding	412	M 2
ш	121.6	DSF(F04)	Deposits Settled Fine	426	M 2
ш	122.2	DAGS(S05)	Deposits Attached Grease	438	M 2
Н	_\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	TF	Tap Factory	535	NA
ш	212.7	ТВ	Tap Break-in	643	NA
ш	245.0	DAGS(F05)	Deposits Attached Grease	719	M 2
н	278.8	MWL	Water Level	798	NA
ш	281.1	DAZ(S06)	Deposits Attached Other	814	M 2
	290.7	DAZ(F06)	Deposits Attached Other	845	M 2
	293.0	AMH	Manhole	861	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: M-802-005



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: DAZ

Description: Deposits Attached Other

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks: Mixed materials




Code: HSV

Description: Hole Soil Visible

Distance (ft): 2.5
Structural Grade: 5
O&M Grade: 0
Clock Start/From: 2

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 4
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:




Code: RFJ

Description: Roots Fine Joint

Distance (ft): 16.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 11

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 29.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 35.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 5

1st Value:

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
NO

Remarks: Mixed materials / Clock positions

vary



Description: Deposits Attached Grease

Distance (ft): 35.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 5

Clock To: 7

1st Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:

2nd Value:



Code: MWL

Description: Water Level

Distance (ft): 51.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO



Description: Deposits Attached Grease

Distance (ft): 55.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks: Clock positions vary



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 65.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 4

Clock To: 8

1st Value:

Value Percent: 10.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:

2nd Value:



Description: Deposits Attached Grease

Distance (ft): 89.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks: Clock positions vary



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 89.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
NO



Code: TBI

Description: Tap Break-in Intruding

Distance (ft): 120.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

2nd Value:




Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 121.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

Value Percent: 10.000
Continuous Index: F04
Within 8" of Joint: NO

Remarks: Clock positions vary



Description: Deposits Attached Grease

Distance (ft): 122.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8
1st Value:


2nd Value: Value Percent:

Value Percent: 10.000
Continuous Index: S05
Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory



Distance (ft): 164.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TB

Description: Tap Break-in

Distance (ft): 212.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 245.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8
1st Value:

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
NO

Remarks: Clock positions vary



Code: MWL

Description: Water Level

Distance (ft): 278.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 35.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 281.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S06
Within 8" of Joint: NO

Remarks: Mixed materials



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 290.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F06
Within 8" of Joint: NO

Remarks: Mixed materials / Clock positions

vary



Code: AMH
Description: Manhole

Distance (ft): 293.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-802-006