Profile/Ph	noto Observation	n Report			RedZo
Date:	03/20/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	t): 304.6	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	John Kuglmaie	r PSR:	P-802-006-007
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	N HOBART RD		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Main Highway - S	uburban/Rural	Tape/Media #:		
Purpose:	Resurvey		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ils:		Direction of Surv	vey: Downstream	
US MH:	M-802-006	DS MH:	M-802-007	Total Length Surveyed (ft)	: 299.2
D&M Index:	2.17	O&M Quick:	362	D O&M Rating:	76.00
Structural Index	. 0.00	Structural Qu	uick: 000	00 Structural Rating:	0.00
Overall Index:	2.17	Overall Quick		Ŭ	76.00

	Position	Code	Observation	Video (sec)	Grade
M-802-0	06				
	.0	AMH	Manhole	10	NA
Ň	.0	MWL	Water Level	22	NA
	\ <u>.</u> 0	DAZ(S01)	Deposits Attached Other	33	M 3
	29.6	TF	Tap Factory	104	NA
	30.3	DAZ(F01)	Deposits Attached Other	117	M 3
_	30.3	MGO	General Observation	130	NA
_	146.9	DAGS(S02)	Deposits Attached Grease	375	M 2
_	177.8	TF	Tap Factory	448	NA
_	293.1	DAGS(F02)	Deposits Attached Grease	691	M 2
5	293.1	MGO	General Observation	704	NA
ecti	299.2	AMH	Manhole	732	NA
Camera Direction					
M-802-0	07				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-802-006



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DAZ
Description:	Deposits Attached Other

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	Mixed materials



Code:	TF
Description:	Tap Factory

Distance (ft):	29.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAZ
Description:	Deposits Attached Other
Distance (ft):	30.3
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	15.000 F01 NO Mixed materials / Clock positions vary



Code:MGODescription:General Observation

Distance (ft):	30.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	Switching to rear camera

DAGS


Deposits Attached Grease



Distance (ft):	146.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	S02
Within 8" of Joint:	NO
Remarks:	

Code:

Description:



Code:	TF
Description:	Tap Factory

Distance (ft):	177.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease
Distance (ft):	293.1

2.0000.000 ().	
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	F02
Within 8" of Joint:	NO
Remarks:	Clock positions vary



Code:MGODescription:General Observation

Distance (ft): 293.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: Switching to front camera

Code: Description: AMH Manhole



Distance (ft):	299.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-802-007