## **Profile/Photo Observation Report**



P-802-007-008

Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 122.0 Owner: NA Pre Clean: **Not Known** P.O.#:

John Kuglmaier

PSR:

Customer: 01/01/1900 Clean Date: Shape:

N HOBART RD Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Main Highway - Suburban/Rural Tape/Media #: Location:

Purpose: Resurvey Dia/Height: 10" **PVC** Use: Sanitary Material:

NA Lining: Drain Area:

NA Category:

Comment:

**Location Details:** Direction of Survey: Upstream

US MH: M-802-007 M-802-008 Total Length Surveyed (ft): DS MH: 117.8

2.09 46.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.09 46.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
802-008	3				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	22	NA
/,	.0	DAGS(S01)	Deposits Attached Grease	33	M 2
	78.6	TF	Tap Factory	202	NA
l F	85.0	OBZ	Obstacle Other	226	M 4
	99.0	DAGS(F01)	Deposits Attached Grease	266	M 2
	106.6	MWL	Water Level	292	NA
	111.0	DAZ(S02)	Deposits Attached Other	313	M 2
	114.4	MWL	Water Level	331	NA
	115.1	DAZ(F02)	Deposits Attached Other	344	M 2
	117.8	AMH	Manhole	360	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-802-008		

 $\mathsf{AMH}$ 

M(802)007



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

25.000

NO



Code: DAGS

Description: **Deposits Attached Grease** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 4 Clock To: 8 1st Value:

Value Percent: 10.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks:

2nd Value:



Code: **TF** 

Description: Tap Factory

Distance (ft): 78.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: OBZ

Description: Obstacle Other

Distance (ft): 85.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 6
Clock To: 9
1st Value:

Value Percent: 30.000

Continuous Index:

2nd Value:

Within 8" of Joint: NO

Remarks: Mixed materials



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 99.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks: Clock positions vary



Code: MWL

Description: Water Level

Distance (ft): 106.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 111.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks: Mixed materials



Code: MWL

Description: Water Level

Distance (ft): 114.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 115.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks: Mixed materials / Clock positions

vary



Code: AMH
Description: Manhole

Distance (ft): 117.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-802-007