## **Profile/Photo Observation Report**



Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 122.0 Owner: NA Pre Clean: **Not Known** P.O.#: John Kuglmaier PSR: P-802-007-008 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Hobart Rd Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Main Highway - Suburban/Rural Tape/Media #:

Purpose: Resurvey Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-802-007 DS MH: M-802-008 Total Length Surveyed (ft): 117.8

2.09 46.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.09 46.00 Overall Quick: Overall Rating: Overall Index:

0	Code	Observation	Video (sec)	Grade
	AMH	Manhole	10	NA
.0	MWL	Water Level	22	NA
.0	DAGS(S01)	Deposits Attached Grease	33	M 2
78.6	TF	Tap Factory	202	NA
85.0	OBZ	Obstacle Other	226	M 4
99.0	DAGS(F01)	Deposits Attached Grease	266	M 2
106.6	MWL	Water Level	292	NA
111.0	DAZ(S02)	Deposits Attached Other	313	M 2
114.4	MWL	Water Level	331	NA
115.1	DAZ(F02)	Deposits Attached Other	344	M 2
117.8	AMH	Manhole	360	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-802-008

 $\mathsf{AMH}$ 



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

25.000

NO

Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8
1st Value:

2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 78.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: OBZ

Description: Obstacle Other

Distance (ft): 85.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 6
Clock To: 9
1st Value:

2nd Value: Value Percent: **30.000** 

Continuous Index:

Within 8" of Joint: NO

Remarks: Mixed materials



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 99.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks: Clock positions vary



Code: MWL

Description: Water Level

Distance (ft): 106.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 111.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks: Mixed materials



Code: MWL

Description: Water Level

Distance (ft): 114.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 115.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks: Mixed materials / Clock positions

vary



Code: AMH
Description: Manhole

Distance (ft): 117.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-802-007