## **Profile/Photo Observation Report**



Date: 03/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 242.6 Owner: NA Pre Clean: **Not Known** P.O.#: John Kuglmaier PSR: P-802-020-008 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Hobart Rd Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Main Highway - Suburban/Rural Tape/Media #:

Purpose: Resurvey Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-802-020 DS MH: M-802-008 Total Length Surveyed (ft): 238.0

2.83 34.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.83 34.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
802-	008				
$\longrightarrow$	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
	\\.0	DAZ(S01)	Deposits Attached Other	32	M 4
ш	24.2	DAZ(F01)	Deposits Attached Other	92	M 4
ш	126.1	MWL	Water Level	308	NA
ш	160.9	DAGS(S02)	Deposits Attached Grease	388	M 2
ш	179.1	DAGS(F02)	Deposits Attached Grease	436	M 2
ш	183.7	DAGS(S03)	Deposits Attached Grease	457	M 2
ш	199.6	DAGS(F03)	Deposits Attached Grease	501	M 2
ш	238.0	AMH	Manhole	589	NA
ш	l IIII				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-802-008

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

15.000

NO

Code: DAZ

Description: **Deposits Attached Other** 



Distance (ft): .0

Structural Grade: 0 O&M Grade: 4 Clock Start/From: 7 Clock To: 5

1st Value: 2nd Value:

Value Percent: 30.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks: **Mixed materials** 



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 24.2
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 30.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks: Mixed materials / Clock positions

vary

Code: MWL

Description: Water Level



Distance (ft): 126.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 160.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 3
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:

1st Value:

Code: DAGS


Description: Deposits Attached Grease



Distance (ft): 179.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 3

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
NO

Remarks: Clock positions vary



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 183.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 11
Clock To: 1
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:

1st Value:

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 199.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 11
Clock To: 1

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
NO

Remarks: Clock positions vary



Code: AMH
Description: Manhole

Distance (ft): 238.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-802-020