Profile/Pho	oto Observation	Report				RedZone
Date: Pipe Length (ft) P.O.#: Customer:	10/02/2018 : 225.0	Weather: Owner: Surveyor: Clean Date	NA Justin Goi : 01/01/19		Coding: Pre Clean: PSR: Shape:	PACP 6.0 Not Known P-903-032-013 C
Street:	E RAND ST & N HO	BART RD	Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Routine Assessme	nt	Dia/Height:	:	12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	5:		Direction o	f Survey:	Downstream	
US MH:	M-803-013	DS MH:	M-903-032		Total Length Surveyed (ft)	: <b>180.6</b>
D&M Index:	1.80	O&M Quick	:	2411	O&M Rating:	9.00
Structural Index:	2.00	Structural C	uick:	2100	Structural Rating:	2.00
Overall Index:	1.83	Overall Quid	ck:	2511	Overall Rating:	11.00

	Position	Code	Observation	Video (sec)	Grade
M(803-0	13				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	52.0	TF	Tap Factory	137	NA
	67.6	RFJ	Roots Fine Joint	180	M 1
	67.6	DAGS	Deposits Attached Grease	191	M 2
	77.3	CL	Crack Longitudinal	223	S 2
	141.6	DAZ	Deposits Attached Other	363	M 2
	157.0	DAZ	Deposits Attached Other	406	M 2
	163.3	TF	Tap Factory	430	NA
5	167.6	DAGS	Deposits Attached Grease	451	M 2
	180.6	MSA	Abandoned Survey	488	NA
Camera Direction					
M-903-0	32				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-013



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 10.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	TF Tap Factory
Distance (ft):	52.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

## Thursday, November 16, 2023



Code:RFJDescription:Roots Fine Joint

Distance (ft):	67.6
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	1
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	67.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:CLDescription:Crack Longitudinal

Distance (ft):	77.3
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	DAZ
Description:	Deposits Attached Other

Distance (ft):	141.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:DAZDescription:Deposits Attached Other

Distance (ft):	157.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	163.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	167.6
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code: Description: MSA Abandoned Survey



Distance (ft):	180.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	<b>ROBOT HAS STOPPED</b>