Profile/Photo Observation Report



Date: 10/01/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 209.4 Owner: NA Pre Clean: **Not Known**

P.O.#: **Michael Carlino** PSR: P-803-016-015 Surveyor: Customer: 01/01/1900

Shape:

ALLEY BETWEEN N LIBERTY ST & N L Flow Control: **Not Controlled** Street:

Clean Date:

City: Hobart, IN Year Renewed:

Tape/Media #: Location: **Light Highway**

Purpose: **Routine Assessment** Dia/Height: 12" Use: Sanitary Material: **VCP**

NA Lining: Drain Area:

NA Category:

Comment:

Location Details: Direction of Survey: Upstream


US MH: Total Length Surveyed (ft): M-803-015 DS MH: M-803-016 29.7

2.38 5133 19.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.38 5133 19.00 Overall Quick: Overall Rating: Overall Index:

.0	АМН			
.0	AMH			
		Manhole	10	NA
0.	MWL	Water Level	20	NA
5.1	RFJ	Roots Fine Joint	41	M 1
7.9	RMJ	Roots Medium Joint	57	M 3
/10.7	RMJ	Roots Medium Joint	73	M 3
//14.0	RFJ	Roots Fine Joint	90	M 1
20.4	TFD	Tap Factory Defective	114	M 2
20.4	RFL	Roots Fine Lateral	124	M 1
25.8	RMJ	Roots Medium Joint	146	M 3
28.7	RBB	Roots Ball Barrel	163	M 5
29.7	MSA	Abandoned Survey	176	NA



AMH Manhole
0
.0
0
0
NO
M-803-016



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

Code:

RFJ

NO

Description: Roots Fine Joint




Distance (ft): 5.1
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9
Clock To: 1
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 7.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 9
Clock To: 4

1st Value: 2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 10.7
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 9

Clock To: 3

1st Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 14.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 10
Clock To: 2

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 20.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: RFL



Code: RFL

Description: Roots Fine Lateral

Distance (ft): 20.4
Structural Grade: 0

O&M Grade: 1


Clock Start/From: 2

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 25.8
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 9

Clock To: 3

1st Value:

Value Percent: 25.000


Continuous Index:

Within 8" of Joint:

Remarks:

2nd Value:

YES



Code: RBB

Description: Roots Ball Barrel

Distance (ft): 28.7
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 9
Clock To: 3

1st Value: 2nd Value:

Value Percent: 85.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 29.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: RBB