Profile/Photo Observation Report



Date: 10/01/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 213.4 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: P-803-017-016 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: 40th. Ave. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-803-016 DS MH: M-803-017 Total Length Surveyed (ft): 203.7

1.67 15.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 1.80 18.00 Overall Quick: Overall Rating: Overall Index:

303-		A N 41 1	NA	10	NIA
	0.	AMH	Manhole	10	NA
Щ	0. /\	MWL	Water Level	21	NA
ш	\\ <u>5.4</u>	TF	Tap Factory	44	NA
ш	14.9	TF	Tap Factory	75	NA
+	35.4	RFJ	Roots Fine Joint	128	M 1
ш	36.7	TF	Tap Factory	142	NA
ш	84.5	TF	Tap Factory	251	NA
ш	104.6	ISSR	Intruding Sealing Ring	303	M 2
ш	//105.4	TF	Tap Factory	317	NA
	115.0	RFJ	Roots Fine Joint	348	M 1
П	//135.0	RFJ	Roots Fine Joint	399	M 1
Ш,	140.7	TF	Tap Factory	423	NA
+	163.7	TF	Tap Factory	482	NA
	179.4	RFJ	Roots Fine Joint	525	M 1
ш	182.5	RFJ	Roots Fine Joint	543	M 1
Ш	186.1	MWLS	Water Level Sag	562	S 3
	188.6	RFJ	Roots Fine Joint	578	M 1
ш	199.2	MCU(S01)	Camera Underwater	611	M 4
Ш	203.7	MSA	Abandoned Survey	632	NA
Ш	203.7	MCU(F01)	Camera Underwater	643	M 4

Code:



Description: Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-803-017

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: TF

Description: **Tap Factory**

Distance (ft): 5.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 14.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 35.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 36.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 84.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

2nd Value:

1st Value: **4.000**

Value Percent: Continuous Index: Within 8" of Joint:



Code: ISSR

Description: Intruding Sealing Ring

Distance (ft): 104.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 5
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 105.4
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 115.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 135.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 140.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 163.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: RFJ

Description: Roots Fine Joint


Distance (ft): 179.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: RFJ

Description: Roots Fine Joint

Distance (ft): 182.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **MWLS**

Description: **Water Level Sag**

Distance (ft): 186.1 Structural Grade: 3 3 O&M Grade: Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 50.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

YES




RFJ Code:

Description: **Roots Fine Joint**

Distance (ft): 188.6 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 8 Clock To: 12 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: Remarks:



Code: MCU

Description: Camera Underwater

Distance (ft): 199.2
Structural Grade: 0
O&M Grade: 4

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: **S01**Within 8" of Joint: **NO**

Remarks:

Code:

Description: Abandoned Survey

MSA



Distance (ft): 203.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: MCU



Code: MCU

Description: Camera Underwater

Distance (ft): 203.7
Structural Grade: 0
O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: NO