## **Profile/Photo Observation Report**



Date: 10/01/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 306.0 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-803-019-020

Customer: Clean Date: 01/01/1900 Shape: C

Street: **E 40TH AVE** Flow Control: **Not Controlled** 

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream


US MH: M-803-019 DS MH: M-803-020 Total Length Surveyed (ft): 291.3

1.20 2114 6.00 O&M Index: O&M Quick: O&M Rating: 2.67 8.00 Structural Quick: Structural Rating: Structural Index: 1.75 14.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
803-02	20				
$\overline{}$	.0	AMH	Manhole	10	NA
<b> </b>	0.	MWL	Water Level	21	NA
	73.8	FM	Fracture Multiple	181	S 4
	73.8	TBI	Tap Break-in Intruding	192	M 2
	86.1	TF	Tap Factory	228	NA
	88.6	TF	Tap Factory	245	NA
	141.2	TF	Tap Factory	363	NA
	144.0	TF	Tap Factory	381	NA
	185.7	CL	Crack Longitudinal	476	S 2
	199.5	TF	Tap Factory	515	NA
	202.0	TF	Tap Factory	531	NA
	262.1	ТВ	Tap Break-in	663	NA
	266.6	TFC	Tap Factory Capped	683	NA
	268.6	TF	Tap Factory	699	NA
	272.0	RFJ	Roots Fine Joint	718	M 1
	277.7	RFJ(S01)	Roots Fine Joint	740	M 1
	285.1	FC	Fracture Circumferential	766	S 2
	291.3	AMH	Manhole	790	NA
	291.3	RFJ(F01)	Roots Fine Joint	801	M 1

Code:


Description:



.0
0
0
NO
M-803-020

AMH

Manhole



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: FM

Description: Fracture Multiple

Distance (ft): 73.8
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 10
Clock To: 2

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TBI

Description: Tap Break-in Intruding

Distance (ft): 73.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2


Clock To:

 1st Value:
 4.000

 2nd Value:
 0.500

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 86.1
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 88.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory


Distance (ft): 141.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

2nd Value:

1st Value: **4.000** 

Value Percent: Continuous Index: Within 8" of Joint:



Code: TF

Description: **Tap Factory** 


Distance (ft): 144.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




CL Code:

Description: **Crack Longitudinal** 

Distance (ft): 185.7 Structural Grade: 2 O&M Grade: 0 Clock Start/From: 1 Clock To: 1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

YES



Code: **TF** 

Description: Tap Factory


Distance (ft): 199.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 


Description: Tap Factory

Distance (ft): 202.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TB

Description: Tap Break-in

Distance (ft): 262.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory Capped

4.000



Distance (ft): 266.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory


Distance (ft): 268.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: RFJ

Description: Roots Fine Joint

Distance (ft): 272.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 8
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: RFJ


Description: Roots Fine Joint

Distance (ft): 277.7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: **S01** Within 8" of Joint: **YES** 

Remarks: WANDER



Code: FC

Description: Fracture Circumferential

Distance (ft): 285.1
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 7
Clock To: 6
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ROOTS COMING FROM FRACTURES



Code: AMH
Description: Manhole

Distance (ft): 291.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-803-019



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 291.3
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER