
Profile/Photo Observation Report						
Date:	10/02/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	): <b>297.7</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Michael C	arlino	PSR:	P-803-027-028
Customer:		Clean Date:	01/01/190	00	Shape:	с
Street:	Rand St.	Flow Control:		Not Controlled		
City:	Hobart, IN		Year Renew	ved:		
Location:	Light Highway		Tape/Media	a #:		
Purpose:	<b>Routine Assessment</b>	t i	Dia/Height:		12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction of	f Survey:	Upstream	
US MH:	M-803-028	DS MH:	M-803-027		Total Length Surveyed (ft)	18.9
0&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
Structural Index:	0.00	 Structural Qu	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quicl	k:	0000	Overall Rating:	0.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-027

Tuesday, December 8, 2020



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	5.5 0 1 6.000
Within 8" of Joint: Remarks:	



Code: MSA Description: Abandoned Survey Distance (ft): 18.9 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: Unknown