Profile/Photo Observation Report



Date: 03/28/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 207.8 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-803-034-035 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: N INDIANA ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Upstream

US MH: M-803-035 DS MH: M-803-034 Total Length Surveyed (ft): 8.0

3100 3.00 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 3.00 3100 3.00 Overall Quick: Overall Rating: Overall Index:


	Position	Code	Observation	Video (sec)	Grade
M(803-)03	34				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
-11	6.3	RMJ	Roots Medium Joint	45	M 3
-11	8.0	MSA	Abandoned Survey	60	NA
Camera Direction	35				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-803-034

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:


Within 8" of Joint: NO

Remarks:

....

Code: RMJ

Description: Roots Medium Joint



Distance (ft): 6.3
Structural Grade: 0
O&M Grade: 3

Clock Start/From: 8
Clock To: 9
1st Value:


2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 8.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped