Profile/Photo Observation Report

1.02

Structural Index:

Overall Index:



48.00

Date: 04/18/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): 230.7 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 PSR: P-803-044-045 Surveyor: SAN **Red Zone** Customer: Clean Date: Shape: 415 Kelly st Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Easement/Right of Way Tape/Media #: Deliverable 1 Location: Purpose: **Routine Assessment** Dia/Height: 15" Use: Sanitary Material: **VCP** Northeast Drain Area: Lining: NA Category: Comment: 413-3 **Location Details: Grass between homes** Direction of Survey: **Downstream** M-803-044 US MH: DS MH: M-803-045 Total Length Surveyed (ft): 230.7 1.02 211H 48.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00

211H

Structural Rating:

Overall Rating:

Structural Quick:

Overall Quick:

Thursday, May 4, 2023 1

	Position	Code	Observation	Video (sec)	Grade
803-0)44				
	0. //	AMH	Manhole	10	NA
Ш,	0.	MWL	Water Level	47	NA
ш	2.3	RFJ(S01)	Roots Fine Joint	114	M 1
	28.6	TF	Tap Factory	163	NA
	34.7	TF	Tap Factory	208	NA
ш	114.8	TFD	Tap Factory Defective	375	M 2
ш	117.8	TFA	Tap Factory Active	426	NA
ш	167.8	TF	Tap Factory	513	NA
ш	230.6	RFJ(F01)	Roots Fine Joint	629	M 1
ш	230.7	AMH	Manhole	659	NA



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-044



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: RFJ

Description: **Roots Fine Joint**

Distance (ft): 2.3 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 8

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: **S01** Within 8" of Joint: YES

Remarks: wanders

3 Thursday, May 4, 2023



Code: **TF**

Description: Tap Factory

Distance (ft): 28.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: Tap Factory

Distance (ft): 34.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 114.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: roots in tap



Code: TFA

Description: Tap Factory Active

Distance (ft): 117.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 167.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 230.6
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks: wanders



Code: AMH
Description: Manhole

Distance (ft): 230.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO
Remarks: M-803-045