Profile/Photo Observation Report



Date: 03/27/2018 Weather: Coding: **PACP 6.0** Pipe Length (ft): 293.8 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-803-069-070

Customer: Clean Date: 01/01/1900 Shape: C

Street: N COLONIAL DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-803-070 DS MH: M-803-069 Total Length Surveyed (ft): 235.4

O&M Index:	2.06	O&M Quick:	4131	O&M Rating:	103.00
Structural Index:	3.00	Structural Quick:	3100	Structural Rating:	3.00
Overall Index:	2.08	Overall Quick:	4132	Overall Rating:	106.00

Position	Code	Observation	Video (sec)	Grade
0.	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
\\.0	DAZ(S01)	Deposits Attached Other	32	M 2
18.2	TF	Tap Factory	81	NA
142.0	TF	Tap Factory	341	NA
148.8	TF	Tap Factory	366	NA
171.0	TF	Tap Factory	422	NA
211.3	DSZ	Deposits Settled Other	517	M 2
232.6	MWLS	Water Level Sag	573	S 3
235.4	MSA	Abandoned Survey	592	NA
235.4	MCU	Camera Underwater	603	M 4
235.4	DAZ(F01)	Deposits Attached Other	615	M 2

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-803-070		

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER



Code: **TF**

Description: Tap Factory


Distance (ft): 18.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 142.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 148.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 171.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 211.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO Remarks: misc



Code: MWLS

Description: Water Level Sag

Distance (ft): 232.6
Structural Grade: 3
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 45.000

Continuous Index:

Within 8" of Joint: NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 235.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: ROBOT HAS STOPPED

Code: MCU

Description: Camera Underwater

Distance (ft): 235.4
Structural Grade: 0

O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 235.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER