


# Profile/Photo Observation Report



Date:	10/22/2021	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	294.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-804-021-020
Customer:	City of Hobart	Clean Date:	09/15/2021	Shape:	C

Street:	North Illinois Street	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Alley	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	8"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Upstream
US MH:	M-804-021	DS MH:	M-804-020
		Total Length Surveyed (ft):	238.4

O&M Index:	1.91	O&M Quick:	5141	O&M Rating:	183.00
Structural Index:	3.00	Structural Quick:	4535	Structural Rating:	45.00
Overall Index:	2.05	Overall Quick:	5146	Overall Rating:	228.00

Position	Code	Observation	Video (sec)	Grade
				
.0	AMH	Manhole	1	NA
.0	MWL	Miscellaneous Water Level	11	NA
1.5	MGO	Miscellaneous General Observation	31	NA
1.5	TFC	Tap Factory Capped	44	NA
2.0	DSF(S04)	Deposits Settled Fine	64	M 2
3.2	TFC	Tap Factory Capped	86	NA
11.8	CM	Crack Multiple	194	S 3
14.1	B	Broken	246	S 4
16.1	FM	Fracture Multiple	294	S 4
24.1	CM	Crack Multiple	383	S 3
28.3	RFJ(S01)	Roots Fine Joint	448	M 1
37.5	TFC	Tap Factory Capped	516	NA
39.6	TFC	Tap Factory Capped	554	NA
63.9	MMC	Miscellaneous Material Change	697	NA
65.3	TS	Tap Saddle	748	NA
66.8	MMC	Miscellaneous Material Change	798	NA
70.7	DAE	Deposits Attached Encrustation	858	M 2
77.8	FM	Fracture Multiple	923	S 4
77.8	TFC	Tap Factory Capped	950	NA

80.0	TFC	Tap Factory Capped	993	NA
88.7	DAE	Deposits Attached Encrustation	1060	M 2
96.7	RFJ(F01)	Roots Fine Joint	1116	M 1
104.3	CM	Crack Multiple	1170	S 3
110.9	DAZ	Deposits Attached Other	1239	M 2
117.9	JOMD	Joint Offset Medium Defective	1279	S 3
118.6	TFC	Tap Factory Capped	1311	NA
121.2	DAE(S02)	Deposits Attached Encrustation	1381	M 2
122.3	TFC	Tap Factory Capped	1408	NA
131.7	B	Broken	1509	S 4
131.8	IRC	Infiltration Runner Connection	1529	M 4
132.0	TBI	Tap Break-in Intruding	1548	M 2
132.2	DAGS(S03)	Deposits Attached Grease	1568	M 2
135.3	DAGS(F03)	Deposits Attached Grease	1601	M 2
150.8	DAE	Deposits Attached Encrustation	1728	M 2
160.0	TFC	Tap Factory Capped	1815	NA
162.1	TFC	Tap Factory Capped	1845	NA
164.1	TBI	Tap Break-in Intruding	1905	M 2
168.8	DAE	Deposits Attached Encrustation	1958	M 2
168.9	OBM	Obstruction Pipe Material in Invert	1975	M 2
170.6	MWLS	Miscellaneous Water Level Sag	2005	S 2
189.0	JOM	Joint Offset Medium	2101	S 3
200.7	TFC	Tap Factory Capped	2161	NA
202.5	TFC	Tap Factory Capped	2186	NA
208.9	MWLS(S05)	Miscellaneous Water Level Sag	2227	S 2
212.5	B	Broken	2293	S 4
214.8	MWLS(F05)	Miscellaneous Water Level Sag	2322	S 2
219.1	MWLS	Miscellaneous Water Level Sag	2358	S 2
225.7	MWLS(S06)	Miscellaneous Water Level Sag	2395	S 2
234.5	TBI	Tap Break-in Intruding	2507	M 2
234.5	MWLS(F06)	Miscellaneous Water Level Sag	2521	S 2
234.8	DSF	Deposits Settled Fine	2540	M 5
238.4	DSF(F04)	Deposits Settled Fine	2767	M 2
238.4	DAE(F02)	Deposits Attached Encrustation	2775	M 2
238.4	MSA	Miscellaneous Survey Abandoned	2783	NA

M-804-021



Code: **AMH**  
 Description: **Manhole**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-804-020**




Code: **MWL**  
 Description: **Miscellaneous Water Level**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MGO**  
 Description: **Miscellaneous General Observation**

Distance (ft): **1.5**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **DROP INTO THE MANHOLE. HAD TO START IN THE PIPE.**



Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **1.5**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **ENCUSTATION AROUND THE CAP**




Code: **DSF**  
 Description: **Deposits Settled Fine**

Distance (ft): **2.0**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S04**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **3.2**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **ENCRUSTATION AROUND THE CAP**




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **11.8**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **B**  
 Description: **Broken**

Distance (ft): **14.1**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **16.1**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **24.1**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **28.3**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **7**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S01**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **37.5**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **39.6**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **63.9**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO PVC**




Code: **TS**  
 Description: **Tap Saddle**

Distance (ft): **65.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **66.8**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **PVC TO VCP**



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **70.7**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **FM**  
 Description: **Fracture Multiple**


Distance (ft): **77.8**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **TFC**  
Description: **Tap Factory Capped**

Distance (ft): **77.8**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **ENCUSRUSTATION AROUND THE CAP**

---



Code: **TFC**  
Description: **Tap Factory Capped**

Distance (ft): **80.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **10**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **ENCUSTATION AROUND THE CAP**

---



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **88.7**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **96.7**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **7**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F01**  
 Within 8" of Joint: **YES**  
 Remarks:

---




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **104.3**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **DAZ**  
 Description: **Deposits Attached Other**

Distance (ft): **110.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **MUD**




Code: **JOMD**  
 Description: **Joint Offset Medium Defective**

Distance (ft): **117.9**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **TFC**  
 Description: **Tap Factory Capped**


Distance (ft): **118.6**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **121.2**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **7**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **S02**  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **TFC**  
Description: **Tap Factory Capped**


Distance (ft): **122.3**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **10**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **B**  
 Description: **Broken**

Distance (ft): **131.7**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **IRC**  
 Description: **Infiltration Runner Connection**

Distance (ft): **131.8**  
 Structural Grade: **0**  
 O&M Grade: **4**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **132.0**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAGS**  
 Description: **Deposits Attached Grease**

Distance (ft): **132.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S03**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAGS**  
 Description: **Deposits Attached Grease**

Distance (ft): **135.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F03**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **150.8**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **160.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **162.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **164.1**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value: **2.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **168.8**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **OBM**  
 Description: **Obstruction Pipe Material in Invert**

Distance (ft): **168.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**


Distance (ft): **170.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:

---




Code: **JOM**  
 Description: **Joint Offset Medium**

Distance (ft): **189.0**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **200.7**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **202.5**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **208.9**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S05**  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **B**  
 Description: **Broken**

Distance (ft): **212.5**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **214.8**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F05**  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **219.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **225.7**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S06**  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **234.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value: **2.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **234.5**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F06**  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **DSF**  
 Description: **Deposits Settled Fine**

Distance (ft): **234.8**  
 Structural Grade: **0**  
 O&M Grade: **5**  
 Clock Start/From: **12**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent: **55.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DSF**  
 Description: **Deposits Settled Fine**

Distance (ft): **238.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F04**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **238.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **7**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F02**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MSA**  
 Description: **Miscellaneous Survey Abandoned**

Distance (ft): **238.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CAMERA CANT MAKE IT PAST DEBRIS**