Profile/Photo Observation Report

0.00

0.00

Structural Quick:

Overall Quick:

Structural Index:

Overall Index:



0.00

0.00

Date: 05/03/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): 40.5 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 PSR: P-804-031-030 Surveyor: SAN **Red Zone** Customer: Clean Date: Shape: 1508 Hickey St Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Tape/Media #: Deliverable 1 Location: **Parking Lot** Purpose: **Routine Assessment** Dia/Height: 10" Use: Sanitary Material: **VCP** Northeast Drain Area: Lining: NA Category: Comment: 442-1/10" diameter pipe. **Location Details:** Flows through easement Direction of Survey: **Downstream** M-804-031 US MH: DS MH: M-804-030 Total Length Surveyed (ft): 40.5 0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating:

0000

0000

Structural Rating:

Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
1(804)0	31				
	.0	AMH	Manhole	16	NA
	\.0	MWL	Water Level	27	NA
ш	35.2	MGO	General Observation	262	NA
ш	40.5	AMH	Manhole	423	NA
(804)03	30				



Code:	AMH	
Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-804-031	



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: MGO

Description: General Observation

Distance (ft): 35.2
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: pipe is dirty





Code: AMH
Description: Manhole

Distance (ft): 40.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-804-030