
		on Report			ROBOTI
Date:	01/17/2025	Weather:		Coding:	PACP 7.0
Pipe Length (ft)	: <b>132.0</b>	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-804-037-035
Customer:	City of Hobart	Clean Date:	11/21/2024	Shape:	С
Street:	<b>Division Street</b>		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Local rural street	s with light traffic,	t Tape/Media #:		
Purpose:	Sewer System Ev	aluation Survey (S	<b>S</b> Dia/Height:	18"	
Use:	Sanitary Sewage	Pipe	Material:	VCP	
Drain Area:			Lining:	None	
Category:	NA				
Comment:					
Location Details	s:		Direction of Surve	ey: Downstream	
US MH:	M-804-037	DS MH:	M-804-035	Total Length Surveyed (ft)	: <b>130.7</b>
D&M Index:	1.81	O&M Quick:	2A13	O&M Rating:	29.00
Structural Index:	2.00	Structural Qu	ick: 3111		4.00
Overall Index:	1.83	Overall Quick	. 312A		33.00

	Position	Code	Observation	Video (sec)	Grade
M-80	04-037				
	.0	AMH	Manhole	0	NA
- 1	.0	MWL	Miscellaneous Water Level	70	NA
- 1	.2	DAGS	Deposits Attached Grease	104	M 2
- 11	16.2	DAE	Deposits Attached Encrustation	193	M 2
- 1	39.6	SSC	Surface Spalling of Damage Coating	287	S 1
- 1	/40.4	DAE	Deposits Attached Encrustation	334	M 2
-1	60.8	DAE	Deposits Attached Encrustation	453	M 2
- 1	69.9	TF	Tap Factory	531	NA
	73.3	TFC	Tap Factory Capped	600	NA
5	///78.7	DAE(S01)	Deposits Attached Encrustation	666	M 2
Camera Direction	82.2	LL	Line Left	696	M 1
	///104.7	СМ	Crack Multiple	840	S 3
e e		ISB	Infiltration Stain Barrel	850	M 1
		TF	Tap Factory	921	NA
۱H	124.8	TFC	Tap Factory Capped	957	NA
LT	124.8	DAE(F01)	Deposits Attached Encrustation	980	M 2
L	129.6	LL	Line Left	1005	M 1
·	130.7	AMH	Manhole	1089	NA
1					
	T				
- 8					
	/]				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-037

Friday, March 21, 2025

M 804-035



Code:	MWL
Description:	Miscellaneous Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	DAGS Deposits Attached Grease
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	.2 0 2 3 9 5.000
Within 8" of Joint: Remarks:	YES




Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	16.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	SSC Surface Spalling of Damage Coating
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	39.6 1 0 3 YES




Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	40.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	DAE Deposits Attached Encrustation
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	60.8 0 2 8 4 5.000 YES



Code: Description:	TF Tap Factory
Distance (ft):	69.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TFC Tap Factory Capped
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	73.3 0 0 1 6.000
Within 8" of Joint: Remarks:	YES ENCRUSTATION COMING FROM THE JOINTS INTO THE MAIN.



Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	78.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01

YES

Within 8" of Joint:

Remarks:



Code: Description:	LL Line Left
Distance (ft):	82.2
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	СМ
Description:	Crack Multiple
	104 7
Distance (ft):	104.7
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	2
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	ISB Infiltration Stain Barrel
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	104.8 0 1 2 5



Code:	TF
Description:	Tap Factory
Distance (ft):	121.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	SERVICE OFFSET FROM THE TAP.



Code: Description:	TFC Tap Factory Capped
Description	
Distance (ft):	124.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	DAE
Description:	Deposits Attached Encrustation
Distance (ft):	124.8
Structural Grade:	0
O&M Grade:	2

8

4

5.000

F01

YES

Clock Start/From:

Continuous Index:

Within 8" of Joint:

Clock To:

1st Value: 2nd Value: Value Percent:

Remarks:

	C. C. C.	0.00 ft/min
	10	A Part
	Mar	
11		Mr. Call
		39
1		
1/17/25		129.60 ft

Code: Description:	LL Line Left
Distance (ft):	129.6
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	130.7 0 0 NO M-804-035