Profile/Photo Observation Report



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 265.8 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-804-050-049 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Ohio St. Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location:OtherTape/Media #:Purpose:Not KnownDia/Height:10"Use:SanitaryMaterial:VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-804-049 DS MH: M-804-050 Total Length Surveyed (ft): 5.2

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
M(804)0	49				
	.0	AMH	Manhole	10	NA
-11	\0	MWL	Water Level	21	NA
-11	5.2	ТВІ	Tap Break-in Intruding	43	M 2
- 11	5.2	MSA	Abandoned Survey	54	NA
Camera Direction					
M(804)0	50				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-804-049	

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO

Code: **TBI**

Description: Tap Break-in Intruding



Distance (ft): 5.2
Structural Grade: 0
O&M Grade: 2

Clock Start/From: 3

Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: unknown