

Profile/Ph	oto Observation	Report				RedZon
Date:	10/04/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	): <b>265.8</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Justin Gonza	les	PSR:	P-804-050-049
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	N OHIO ST		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	:		
Location:	Light Highway		Tape/Media #			
Purpose:	Routine Assessmen	t	Dia/Height:		12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of Su	irvey:	Downstream	
US MH:	M-804-049	DS MH:	M-804-050	Tota	Length Surveyed (ft)	264.5
0&M Index:	2.00	O&M Quick:	2	100	O&M Rating:	2.00
tructural Index:	0.00	 Structural Qu	iick: 0	000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	.: 2	100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M(804)	049				
$\vdash$	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	$\sqrt{4.9}$	ТВ	Tap Break-in	43	NA
	24.0	TF	Tap Factory	93	NA
_	74.2	TF	Tap Factory	204	NA
_	96.6	TF	Tap Factory	261	NA
	//101.2	DAZ	Deposits Attached Other	281	M 2
	// 123.9	ТВ	Tap Break-in	338	NA
	_// / 139.3	TF	Tap Factory	381	NA
s <b>1</b>	//157.3	TF	Tap Factory	429	NA
ecti	///200.8	TF	Tap Factory	528	NA
	///219.2	TFA	Tap Factory Active	577	NA
Camera Direction	264.5	AMH	Manhole	679	NA
M-804-	050				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
	-
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-049

\_\_\_\_



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TB Tap Break-in
Distance (ft):	4.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:TFDescription:Tap Factory

Distance (ft):	24.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TF
Description:	Tap Factory
Distance (ft):	74.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To: 1st Value: 2nd Value: Value Percent:	4.000
Continuous Index: Within 8" of Joint: Remarks:	



Code: TF Description: Tap Factory

96.6
0
0
9
4.000




Code:	DAZ
Description:	Deposits Attached Other

Distance (ft):	101.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:TBDescription:Tap Break-in

Distance (ft):	123.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value:	139.3 0 0 3 4.000
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	157.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




TF Tap Factory
200.8
0
0
3
4.000



Code: Description: TFA Tap Factory Active

Distance (ft):	219.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	264.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-050