Profile/Photo Observation Report



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 277.3 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Byrd Fitzgerald** PSR: P-804-051-050

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Ohio St. Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-804-050 DS MH: M-804-051 Total Length Surveyed (ft): 58.1

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 3121 2.50 5.00 Overall Index: Overall Quick: Overall Rating:

M(804)051 O		sition Code	Observation	V	ideo (sec) Grade
.0 AMH Manhole 10 NA .0 MWL Water Level 21 NA 4.4 TF Tap Factory 42 NA 34.8 TF Tap Factory 116 NA 38.5 FS Fracture Spiral 137 S 3 55.2 DSZ Deposits Settled Other 181 M 2 58.1 MSA Abandoned Survey 199 NA	804-051				
4.4 TF Tap Factory 42 NA 34.8 TF Tap Factory 116 NA 38.5 FS Fracture Spiral 137 S 3 55.2 DSZ Deposits Settled Other 181 M 2 58.1 MSA Abandoned Survey 199 NA	<u></u>	AMH	Manhole	10) NA
34.8 TF Tap Factory 116 NA 38.5 FS Fracture Spiral 137 S 3 55.2 DSZ Deposits Settled Other 181 M 2 58.1 MSA Abandoned Survey 199 NA	0.	MWL	. Water Level	21	L NA
38.5 FS Fracture Spiral 137 S 3 55.2 DSZ Deposits Settled Other 181 M 2 58.1 MSA Abandoned Survey 199 NA	4.4	TF	Tap Factory	42	NA NA
55.2 DSZ Deposits Settled Other 181 M 2 58.1 MSA Abandoned Survey 199 NA	34.	8 TF	Tap Factory	11	L6 NA
58.1 MSA Abandoned Survey 199 NA	38.	5 FS	Fracture Spiral	13	37 S 3
	55.	2 DSZ	Deposits Settled Other	r 18	31 M 2
	58.	1 MSA	Abandoned Survey	19	99 NA
III					

Code:



Manhole
.0
0
0
NO
M-804-051

 AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory



Distance (ft): 4.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 34.8 Structural Grade: 0 0 O&M Grade: Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FS

Description: **Fracture Spiral**

Distance (ft): 38.5 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 11 Clock To: 1 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 55.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO
Remarks: tissue



Code: MSA

Description: Abandoned Survey

Distance (ft): 58.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: no blockage