Profile/Photo Observation Report



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 204.3 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-804-052-023 Surveyor: **Mark Ruby**

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Kelly St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:
Location Details: Direction of Survey:

US MH: M-804-052 DS MH: M-804-023 Total Length Surveyed (ft): 175.3

2.50 5131 10.00 O&M Index: O&M Quick: O&M Rating: 3.94 134.00 Structural Quick: Structural Rating: Structural Index: 144.00 3.79 **514E** Overall Quick: Overall Rating: Overall Index:

Downstream

804	.0 .0	AMH	Manhole	10	NA
	.//\		Water Level	21	
ш	.0	MWL			NA S.4
ш	4.7	FM	Fracture Multiple	42	S 4
ш	5.5	TF	Tap Factory	56	NA
ш	7.4	TF	Tap Factory	71	NA
ш	7.6	TF	Tap Factory	84	NA
ш	9.1	FS	Fracture Spiral	99	S 3
ш	15.3	FS	Fracture Spiral	123	S 3
	21.7	FM(S01)	Fracture Multiple	150	S 4
Н	√ √58.6	TF	Tap Factory	237	NA
ш	\\60.6	TF	Tap Factory	253	NA
ш	\\ 69.1	TBA	Tap Break-in Active	282	NA
ш	105.9	TF	Tap Factory	368	NA
ш	107.8	TF	Tap Factory	384	NA
	119.4	RFJ	Roots Fine Joint	419	M 1
ш	162.0	RFJ	Roots Fine Joint	516	M 1
ш	164.2	RMJ	Roots Medium Joint	532	M 3
ш	174.3	RBB	Roots Ball Barrel	564	M 5
ш	175.3	FM(F01)	Fracture Multiple	577	S 4
ш	175.3	MSA	Abandoned Survey	588	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-804-052		

 AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FM

Description: **Fracture Multiple**

Distance (ft): 4.7 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Description: Tap Factory


Distance (ft): 5.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 7.4
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 10

Clock To:

2nd Value:

1st Value: **4.000**

Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 7.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: FS

Description: Fracture Spiral



Distance (ft): 9.1
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 8
Clock To: 11

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: FS

Description: Fracture Spiral

Distance (ft): 15.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 11

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

S01



Code: FM

Description: Fracture Multiple

Distance (ft): 21.7
Structural Grade: 4

O&M Grade: 0


Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:



Description: Tap Factory

Distance (ft): 58.6
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 60.6
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 69.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory


Distance (ft): 105.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Description: Tap Factory


Distance (ft): 107.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 119.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 12
Clock To:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 162.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint


Distance (ft): 164.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To: 5
1st Value:

2nd Value: Value Percent:

/alue Percent: 10.000

Continuous Index: Within 8" of Joint:

ithin 8" of Joint: YES



Code: RBB

Description: Roots Ball Barrel

Distance (ft): 174.3
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 12
Clock To: 12
1st Value:

2nd Value:

Value Percent: **55.000**


Continuous Index:

Within 8" of Joint:

Remarks:

NO

F01



Code: FM

Description: Fracture Multiple


Distance (ft): 175.3
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value: 2nd Value: Value Percent:

Within 8" of Joint:

Continuous Index:

Remarks:

Tuesday, December 8, 2020



Code: MSA

Description: Abandoned Survey

Distance (ft): 175.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: RBB