## **Profile/Photo Observation Report**



Date: 04/09/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 215.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-804-056-055 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Kelly St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-804-056 DS MH: M-804-055 Total Length Surveyed (ft): 3.1

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
M(804)0	55				
	.0	AMH	Manhole	10	NA
-11	\0	MWL	Water Level	21	NA
-11	3.1	MCU	Camera Underwater	39	M 4
-11	3.1	MSA	Abandoned Survey	50	NA
Camera Direction					
M(804)0	56				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-055

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

100.000

NO

3.1

0

4

Code: MCU Description: **Camera Underwater** 

Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO





Code: MSA

Description: Abandoned Survey

Distance (ft): 3.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: mcu