Profile/Photo Observation Report

2.00

1.85

Structural Quick:

Overall Quick:

Structural Index:

Overall Index:



4.00

48.00

Date: **PACP 4.2** 04/13/2018 Weather: Coding: Pipe Length (ft): 252.0 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 PSR: P-803-054-061 Surveyor: SAN **Red Zone** Customer: Clean Date: Shape: 331 Linda Ave Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Tape/Media #: Deliverable 1 Location: **Light Highway** Purpose: **Routine Assessment** Dia/Height: 15" Use: Sanitary Material: **VCP** Northeast Drain Area: Lining: NA Category: Comment: 404-1/Unable to open M803-054/Manhole 061 is the downstream manhole. **Location Details: Edge of street** Direction of Survey: Upstream M-803-054 Total Length Surveyed (ft): US MH: DS MH: M-803-061 252.0 1.83 3726 44.00 O&M Index: O&M Quick: O&M Rating:

2200

3728

Structural Rating:

Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
803	-061				
	0.0	АМН	Manhole	11	NA
П	.0	MWL	Water Level	25	NA
П	6.2	RFJ(S01)	Roots Fine Joint	162	M 1
Н	√√9.1	TFD	Tap Factory Defective	199	M 2
ш	15.8	RFJ(F01)	Roots Fine Joint	252	M 1
Н	¬ \\\\\\\\\ 15.8	RMJ(S02)	Roots Medium Joint	281	M 3
ш	31.4	RMJ(F02)	Roots Medium Joint	317	M 3
	31.4	RFJ(S03)	Roots Fine Joint	367	M 1
Н	49.6	TFD	Tap Factory Defective	454	M 2
ш	49.6	RMC	Roots Medium Connection	488	M 3
ш	49.7	OBZ(S04)	Obstacle Other	514	M 2
	64.2	MWL	Water Level	603	NA
ш	64.2	OBZ(F04)	Obstacle Other	613	M 2
ш	71.2	TFD	Tap Factory Defective	664	M 2
ш	78.3	RFJ(F03)	Roots Fine Joint	711	M 1
ш	78.6	MWL	Water Level	781	NA
ш	100.6	OBZ	Obstacle Other	921	M 3
ш	102.0	TF	Tap Factory	962	NA
ш	176.8	TFA	Tap Factory Active	1113	NA
Н	179.9	TF	Tap Factory	1158	NA
Н	187.1	MWLS(S05)	Water Level Sag	1207	S 2
Н	198.2	TFB	Tap Factory Abandoned	1341	NA
ш	198.2	MWLS(F05)	Water Level Sag	1364	S 2
Н	-√ 198.2	MWL	Water Level	1379	NA
	216.7	TFB	Tap Factory Abandoned	1452	NA
	243.5	ТВ	Tap Break-in	1561	NA
	252.0	AMH	Manhole	1639	NA



Code: AMH Description: Manhole

Distance (ft): .0 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-902-061



MWL Code:

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 6.2
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 10
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES**

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 9.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

2nd Value:

1st Value: **6.000**

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: roots in tap



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 15.8
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 10

Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 15.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 2
Clock To: 5
1st Value:

2nd Value:

Value Percent: 15.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks: wanders



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 31.4
Structural Grade: 0

O&M Grade: 3


Clock Start/From: 2

Clock To: 5

1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F02
Within 8" of Joint: YES

Remarks: wanders



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 31.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 5
1st Value:
2nd Value:

Value Percent:
Continuous Index:

Continuous Index: \$03
Within 8" of Joint: YES

Remarks: wanders



Code: **TFD**

Description: **Tap Factory Defective**

Distance (ft): 49.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 9

Clock To:

1st Value: 6.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: rootball in tap



RMC Code:

Description: **Roots Medium Connection**

Distance (ft): 49.6 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 7 Clock To: 10 1st Value:


2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: OBZ

Description: **Obstacle Other**

49.7 Distance (ft): Structural Grade: 0 2 O&M Grade: Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: **S04** Within 8" of Joint: NO Remarks: debris



MWL Code:

Description: **Water Level**

Distance (ft): 64.2 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: OBZ

Description: Obstacle Other

Distance (ft): 64.2
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F04
Within 8" of Joint: NO
Remarks: debris



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 71.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2


Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: roots in tap



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 78.3
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F03
Within 8" of Joint: YES

Remarks: wanders



Code: MWL

Description: Water Level

Distance (ft): **78.6**Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

ırks



Code: OBZ

Description: Obstacle Other

Distance (ft): 100.6
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO Remarks: debris



Code: TF

Description: **Tap Factory**

Distance (ft): 102.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 176.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: Tap Factory

Distance (ft): 179.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9


Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Water Level Sag

Distance (ft): 187.1
Structural Grade: 2
O&M Grade: 3

Clock Start/From: Clock To: 1st Value:

1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S05
Within 8" of Joint: NO

Remarks:



Code: TFB

Description: Tap Factory Abandoned

Distance (ft): 198.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: soil in tap



ÚSMH: M-803-054 - DSMH: M-902-06

Water Level

Code: **MWLS**

Description: **Water Level Sag**

Distance (ft): 198.2 Structural Grade: 2 3 O&M Grade:

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 20.000 Continuous Index: F05 Within 8" of Joint: NO

Remarks:

MWL Code:

Description: Water Level

Distance (ft): 198.2 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TFB**

Description: Tap Factory Abandoned

Distance (ft): 216.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: soil in tap



Code: TB

Description: Tap Break-in

Distance (ft): 243.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 252.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-803-054