

Profile/Photo Observation Report



Date:	05/04/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	.0	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-904-052-062
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	197 N Hobart Rd	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Easement/Right of Way	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	18"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	443-2		
Location Details:	Grass between homes	Direction of Survey:	Upstream
US MH:	M-904-052	DS MH:	M-804-062
		Total Length Surveyed (ft):	9.5

O&M Index:	5.00	O&M Quick:	5100	O&M Rating:	5.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	5.00	Overall Quick:	5100	Overall Rating:	5.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	9	NA
	.0	MWL	Water Level	41	NA
	7.0	OBZ	Obstacle Other	104	M 5
	9.4	MGO	General Observation	275	NA
	9.5	MSA	Abandoned Survey	303	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-062




Code: **MWL**
Description: **Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **15.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **OBZ**
Description: **Obstacle Other**

Distance (ft): **7.0**
Structural Grade: **0**
O&M Grade: **5**
Clock Start/From: **3**
Clock To: **8**
1st Value:
2nd Value:
Value Percent: **45.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **debris**



Code:	MGO
Description:	General Observation
Distance (ft):	9.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera will not pass debris



Code:	MSA
Description:	Abandoned Survey
Distance (ft):	9.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	attempt reverse setup