Profile/Photo Observation Report



Date: 04/06/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 236.8 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-804-066-065 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Hobart St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-804-065 DS MH: M-804-066 Total Length Surveyed (ft): 51.1

3121 2.50 5.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.33 3122 7.00 Overall Quick: Overall Rating: Overall Index:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-065

 AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: ID

Description:


Infil Dripper

Distance (ft): 17.2 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 1

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Clock To:



Code: CL

Description: Crack Longitudinal

Distance (ft): 17.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 11

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: **Tap Factory**

Distance (ft): 29.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 29.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 51.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: debris