
Profile/Ph	oto Observation	Report			RedZon
Date:	10/05/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 236.8	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Michael Carling	PSR:	P-804-066-065
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Hobart Rd.		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessmen	t	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detail	ls:		Direction of Surv	ey: Downstream	
US MH:	M-804-065	DS MH:	M-804-066	Total Length Surveyed (ft)	: 13.9
0&M Index:	2.00	O&M Quick:	210	0 O&M Rating:	2.00
tructural Index:	0.00	 Structural Qu	ick: 000	0 Structural Rating:	0.00
Overall Index:	2.00	Overall Quick	. 210	0 Overall Rating:	2.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-804-065


Tuesday, December 8, 2020



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSZ
Description:	Deposits Settled Other
Distance (ft):	12.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	mixed material



Code:MSADescription:Abandoned Survey

Distance (ft):	13.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	DSZ