Profile/Photo Observation Report



Date: 03/28/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 303.5 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: PSR: P-804-072-073 Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: HIGH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-804-073 DS MH: M-804-072 Total Length Surveyed (ft): 302.1

2.00 2400 8.00 O&M Index: O&M Quick: O&M Rating: 4.50 5141 9.00 Structural Quick: Structural Rating: Structural Index: 2.83 17.00 5141 Overall Index: Overall Quick: Overall Rating:


Position	Code	Observation	Video (sec)	Grade
804-073				
.0	AMH	Manhole	10	NA
0./\	MWL	Water Level	21	NA
13.1	D	Deformed	59	S 4
16.1	OBI	Obstacle Intruding Thru Wall	76	M 2
16.3	HVV	Hole Void Visible	88	S 5
16.3	IW	Infil Weeper	99	M 2
16.3	IW	Infil Weeper	111	M 2
16.3	DAE	Deposits Attached Encrustation	122	M 2
96.1	TFA	Tap Factory Active	294	NA
225.2	TFA	Tap Factory Active	566	NA
302.1	AMH	Manhole	731	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-804-073		

 AMH



Code: MWL
Description: Water Level

Distance (ft): .0

Structural Grade: **0**O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code:

Description: **Deformed**

Distance (ft): 13.1
Structural Grade: 4
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: OBI

Description: Obstacle Intruding Thru Wall

Distance (ft): 16.1
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 10

Clock To: 2

1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **HVV**

Description: Hole Void Visible

Distance (ft): 16.3
Structural Grade: 5
O&M Grade: 0
Clock Start/From: 10
Clock To: 2
1st Value:
2nd Value:

Continuous Index: Within 8" of Joint:

Value Percent:

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 16.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 10

1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 16.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Within 8" of Joint: Remarks:

Continuous Index:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 16.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TFA

Description: Tap Factory Active

Distance (ft): 96.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 225.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 302.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-804-072