Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (f	10/19/2021 it):	Weather: Owner:	Hobart,	IN	G	PACP 6.0 Not Known		
P.O.#:	888_1	Surveyor:	M. Piela	icha	PSR:	P-804-UNK-074		
Customer:	Hobart, IN	Clean Date:			Shape:	С		
Street: Off Indiana Street		Flow Control:		Not Controlled	Not Controlled			
City:	Hobart, IN		Year Rene	ewed:				
Location:	ocation: Yard		Tape/Media #:		888	888		
Purpose:	Reversal		Dia/Heigh	nt:	10"			
Use:	Sanitary		Material:		СР			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Deta	ils:		Direction	of Survey:	Downstream			
US MH:	M-804-74	DS MH:	M-804-74		Total Length Surveyed (ft):	.1		
O&M Index:	4.00	O&M Quick:		4100	O&M Rating:	4.00		
Structural Index	O.00	— Structural Qu	uick:	0000	Structural Rating:	0.00		
Overall Index:	4.00	Overall Quicl	k:	4100	Overall Rating:	4.00		

Wednesday, May 3, 2023

Pos	sition Code	Observation	Video (sec)	Grade
(-804) -74				
.0	АМН	Manhole	0	NA
0.	MWL	Water Level	7	NA
0.	DSF	Deposits Settled Fine	13	M 4
\.0	MSA	Abandoned Survey	21	NA

Camera Direction



AMH
Manhole
.0
0
0
NO
M-804-74

Wednesday, May 3, 2023



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 0.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): .0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 4
Clock To: 8
1st Value:
2nd Value:

Value Percent: **30.000**

Continuous Index:

Within 8" of Joint: NO

Remarks:

Wednesday, May 3, 2023 3



Code: MSA

Description: Abandoned Survey

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: deep sdiment