## **Profile/Photo Observation Report**



Profile/Photo Observation Report									
Date: Pipe Length (ft	194	Weather: Owner: Surveyor:	City of Hob M. Pielacha		Coding: Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning P-805-002-003			
Customer:	City of Hobart	Clean Date:			Shape:	<u>C</u>			
Street:	<b>Hobart Road</b>		Flow Control	:	Not Controlled				
City:	Hobart, IN		Year Renewe	d:					
Location:	<b>Light Highway</b>		Tape/Media	#:	<b>DEP 194</b>				
Purpose:	<b>Routine Assessment</b>		Dia/Height:		18"				
Use:	Sanitary		Material:		VCP				
Drain Area:			Lining:						
Category:	NA								
Comment:	5-21-2018								
Location Details:			Direction of Survey:		Downstream				
US MH:	M-805-003	DS MH:	M-805-002		Total Length Surveyed (ft):	312.3			
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00			
Structural Index	. 0.00	— Structural Qı	uick:	0000	Structural Rating:	0.00			
Overall Index:	0.00	 _Overall Quicl	<b>c</b> :	0000	Overall Rating:	0.00			

Thursday, May 4, 2023 1

P	osition	Code	Observation	Video (sec)	Grade
M(805)003					
0.	)	AMH	Manhole	0	NA
\.0	)	MWL	Water Level	8	NA
31	12.3	АМН	Manhole	395	NA
Camera Direction  M.805-002					

Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-805-002

**AMH** 

Thursday, May 4, 2023 2



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 312.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-805-003

Thursday, May 4, 2023 3