

Date:	04/19/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	267.0	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Byrd Fitzgerald	PSR:	P-805-050-051
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Georgianna St.		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	8"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details:			Direction of Surve	ey: Downstream	
US MH:	И-805-051	DS MH:	M-805-050	Total Length Surveyed (ft)	: 163.1
D&M Index:	1.30	O&M Quick:	3422	O&M Rating:	43.00
Structural Index:	3.03	Structural Qu	lick: 413E		103.00
Overall Index:	2.18	Overall Quick	44.25		146.00

	Position	Code	Observation	Video (sec)	Grade
M-805-	051				
$\rightarrow$	0.	AMH	Manhole	10	NA
- 11	.0	MWL	Water Level	22	NA
- 11	.0	FM	Fracture Multiple	33	S 4
	_ \ <u>.</u> 0	CM(S01)	Crack Multiple	44	S 3
- 11	25.7	RFJ(SO2)	Roots Fine Joint	107	M 1
- 11	52.0	RMJ(S03)	Roots Medium Joint	171	M 3
- 11	69.5	RMJ(F03)	Roots Medium Joint	217	M 3
	_/ /76.5	TFC	Tap Factory Capped	243	NA
	//83.1	ТВ	Tap Break-in	269	NA
5	///101.1	TFC	Tap Factory Capped	318	NA
Camera Direction	-///102.9	TFD	Tap Factory Defective	334	M 2
i i	_////114.2	MGO	General Observation	368	NA
nera	_/ // 142.4	TBI	Tap Break-in Intruding	436	M 2
Car	153.4	TF	Tap Factory	470	NA
	163.1	MSA	Abandoned Survey	501	NA
		CM(F01)	Crack Multiple	512	S 3
↓	163.1	RFJ(F02)	Roots Fine Joint	523	M 1
- 11					
- 11					
	_  <b>  </b>				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-805-051

M(805)050




Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:




FM Fracture Multiple
.0
4
0
12
12



Code:	СМ
Description:	Crack Multiple

Distance (ft):	.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	
Remarks:	



RFJ
<b>Roots Fine Joint</b>
25.7
0
1
11
S02
YES
wandering



Code:RMJDescription:Roots Medium Joint

Distance (ft):	52.0
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	2
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	S03
Within 8" of Joint:	YES
Remarks:	wandering

Code:	
Description:	


RMJ Roots Medium Joint

Distance (ft):	69.5
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	2
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	F03
Within 8" of Joint:	YES
Remarks:	wandering



Code:TFCDescription:Tap Factory Capped

Distance (ft):	76.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TB Tap Break-in
Distance (ft):	83.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:TFCDescription:Tap Factory Capped

Distance (ft):	101.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TFD
Description:	Tap Factory Defective
Distance (ft):	102.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	

blocked

Remarks:



Code:MGODescription:General Observation

Distance (ft):	114.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	chipped at joint

Code:

Description:



Distance (ft):	142.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	2.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	

TBI

Tap Break-in Intruding

Tuesday, December 8, 2020




Code:	TF
Description:	Tap Factory

Distance (ft):	153.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	MSA
Description:	Abandoned Survey
·	
Distance (ft):	163.1
Structural Grade:	0
O&M Grade:	0

	•
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris under water



Code:CMDescription:Crack Multiple

Distance (ft):	163.1
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	
Remarks:	

Code:

Description:



Distance (ft):	163.1
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	wandering

RFJ

**Roots Fine Joint**