## **Profile/Photo Observation Report**



Profile/Photo Observation Report								
Date: Pipe Length (ft P.O.#:	144	Weather: Owner: Surveyor:	City of Hol M. Pielach		Pre Clean: PSR: F	PACP 6.0 No Pre-Cleaning P-805-055-054		
Customer:	City of Hobart	Clean Date:			Shape: C	2		
Street:	Lillian Street		Flow Contro	ol:	Not Controlled			
City:	Hobart, IN		Year Renew	ed:				
Location:	<b>Light Highway</b>		Tape/Media	a #:	<b>DEP 144</b>			
Purpose:	<b>Routine Assessment</b>		Dia/Height:		15"			
Use:	Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:	5-21-2018							
Location Detai	ls:		Direction of	Survey:	Downstream			
US MH:	M-805-055	DS MH:	M-805-054		Total Length Surveyed (ft):	.1		
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00		
Structural Index:	0.00	 _Structural Qu	uick:	0000	Structural Rating:	0.00		
Overall Index:	0.00	 _Overall Quicl	k:	0000	Overall Rating:	0.00		

Thursday, May 4, 2023

ſ	Position	Code	Observation	Video (sec)	Grade
M(805-055	ı				
	0	AMH	Manhole	0	NA
\\.\\.\\.\\.\\.\\.\\.\\.\\\.\\\.\\\\.\\\\	0	MWL	Water Level	11	NA
\.	0	MSA	Abandoned Survey	60	NA
Camera Direction  W.805-054					

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-805-055

 $\mathsf{AMH}$ 

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 80.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: **Abandoned Survey** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: heavy sediment/debris

NO

3 Thursday, May 4, 2023