

# Profile/Photo Observation Report



Date:	01/21/2023	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	402.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-805-056-055
Customer:	City of Hobart	Clean Date:	12/19/2022	Shape:	C

Street:	South Lillian Street	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Local rural streets with light traffic, t	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	15"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Downstream
US MH:	M-805-056	DS MH:	M-805-055
		Total Length Surveyed (ft):	396.6

O&M Index:	1.65	O&M Quick:	4137	O&M Rating:	86.00
Structural Index:	3.91	Structural Quick:	514I	Structural Rating:	227.00
Overall Index:	2.85	Overall Quick:	514I	Overall Rating:	313.00

Position	Code	Observation	Video (sec)	Grade
M-805-056				
.0	AMH	Manhole	1	NA
.0	MWL	Miscellaneous Water Level	92	NA
3.4	JAM	Joint Angular Medium	174	S 3
11.7	CM	Crack Multiple	245	S 3
12.9	TFD	Tap Factory Defective	276	M 3
20.0	FM	Fracture Multiple	437	S 4
23.7	FM	Fracture Multiple	519	S 4
31.4	TF	Tap Factory	690	NA
34.6	FM	Fracture Multiple	743	S 4
36.6	SSS	Surface Damage Surface Spalling	799	S 2
36.6	B	Broken	828	S 4
36.6	B	Broken	851	S 4
47.0	RFJ(S01)	Roots Fine Joint	948	M 1
52.1	DAGS	Deposits Attached Grease	1019	M 2
59.6	DAR	Deposits Attached Ragging	1079	M 2
60.7	DAGS(S02)	Deposits Attached Grease	1099	M 2
71.8	RMB	Roots Medium Barrel	1212	M 4
96.6	SZ	Surface Damage Other	1392	NA
96.6	B	Broken	1432	S 4


98.2	DAR	Deposits Attached Ragging	1456	M 2
108.2	TFD	Tap Factory Defective	1582	M 3
109.1	FM	Fracture Multiple	1660	S 4
115.0	RFJ(F01)	Roots Fine Joint	1702	M 1
123.2	DAGS(F02)	Deposits Attached Grease	1742	M 2
142.2	FM	Fracture Multiple	1841	S 4
152.5	BSV	Broken Soil Visible	1939	S 5
154.6	FM	Fracture Multiple	2008	S 4
154.6	FM	Fracture Multiple	2030	S 4
168.1	TFD	Tap Factory Defective	2149	M 3
173.3	FM	Fracture Multiple	2201	S 4
183.5	SZ	Surface Damage Other	2278	NA
191.8	FM(S03)	Fracture Multiple	2437	S 4
218.8	SZ	Surface Damage Other	2612	NA
224.1	TF	Tap Factory	2678	NA
255.2	TF	Tap Factory	2840	NA
297.1	TBD	Tap Break-in/Hammer Defective	3045	M 3
298.5	TBD	Tap Break-in/Hammer Defective	3124	M 3
301.0	TFD	Tap Factory Defective	3172	M 3
317.4	TFD	Tap Factory Defective	3272	M 3
318.5	RFJ	Roots Fine Joint	3348	M 1
326.8	RFJ	Roots Fine Joint	3431	M 1
334.3	DAR	Deposits Attached Ragging	3475	M 2
347.4	JAL	Joint Angular Large	3588	S 4
347.4	RFJ	Roots Fine Joint	3598	M 1
353.3	RFJ(S04)	Roots Fine Joint	3683	M 1
353.3	JAM	Joint Angular Medium	3696	S 3
354.4	TF	Tap Factory	3742	NA
357.2	TBI	Tap Break-in Intruding	3826	M 2
362.8	LL	Line Left	3863	M 1
372.0	JAM	Joint Angular Medium	3947	S 3
375.6	LR	Line Right	3976	M 1
382.1	SZ	Surface Damage Other	4011	NA
394.0	FM(F03)	Fracture Multiple	4134	S 4
394.0	RFJ(F04)	Roots Fine Joint	4142	M 1
396.6	AMH	Manhole	4294	NA

M-805-055




Code: **AMH**  
 Description: **Manhole**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-805-056**



Code: **MWL**  
 Description: **Miscellaneous Water Level**


Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **JAM**  
Description: **Joint Angular Medium**

Distance (ft): **3.4**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **11.7**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **8**  
Clock To: **10**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **TFD**  
 Description: **Tap Factory Defective**

Distance (ft): **12.9**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **10**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **TAP BROKEN. SERVICE LARGE OFFSET. SOIL VISIBLE AT MULTIPLE J**


---



Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **20.0**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **FM**  
Description: **Fracture Multiple**

Distance (ft): **23.7**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **7**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **TF**  
Description: **Tap Factory**


Distance (ft): **31.4**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To:  
1st Value: **6.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **34.6**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **SSS**  
 Description: **Surface Damage Surface Spalling**


Distance (ft): **36.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **B**  
Description: **Broken**

Distance (ft): **36.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **B**  
Description: **Broken**


Distance (ft): **36.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **7**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **47.0**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S01**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAGS**  
 Description: **Deposits Attached Grease**

Distance (ft): **52.1**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code:	<b>DAR</b>
Description:	<b>Deposits Attached Ragging</b>
Distance (ft):	<b>59.6</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>2</b>
Clock Start/From:	<b>6</b>
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>5.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	




Code:	<b>DAGS</b>
Description:	<b>Deposits Attached Grease</b>
Distance (ft):	<b>60.7</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>2</b>
Clock Start/From:	<b>10</b>
Clock To:	<b>2</b>
1st Value:	
2nd Value:	
Value Percent:	<b>5.000</b>
Continuous Index:	<b>S02</b>
Within 8" of Joint:	<b>YES</b>
Remarks:	



Code: **RMB**  
 Description: **Roots Medium Barrel**

Distance (ft): **71.8**  
 Structural Grade: **0**  
 O&M Grade: **4**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent: **40.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **SZ**  
 Description: **Surface Damage Other**

Distance (ft): **96.6**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **A PIECE CHIPPED AWAY FROM THE JOINT.**




Code: **B**  
 Description: **Broken**

Distance (ft): **96.6**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAR**  
 Description: **Deposits Attached Ragging**

Distance (ft): **98.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **7**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code:	<b>TFD</b>
Description:	<b>Tap Factory Defective</b>
Distance (ft):	<b>108.2</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>TAP BROKEN. SERVICE BROKEN. OFFSET AND ANGLED. VOID AND SOI</b>

---



Code:	<b>FM</b>
Description:	<b>Fracture Multiple</b>
Distance (ft):	<b>109.1</b>
Structural Grade:	<b>4</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>7</b>
Clock To:	<b>4</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	

---



Code: **RFJ**  
Description: **Roots Fine Joint**

Distance (ft): **115.0**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **9**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F01**  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **DAGS**  
Description: **Deposits Attached Grease**

Distance (ft): **123.2**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **10**  
Clock To: **2**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **F02**  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **142.2**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **BSV**  
 Description: **Broken Soil Visible**

Distance (ft): **152.5**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **FM**  
Description: **Fracture Multiple**

Distance (ft): **154.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **7**  
Clock To: **9**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **FM**  
Description: **Fracture Multiple**


Distance (ft): **154.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **3**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code:	<b>TFD</b>
Description:	<b>Tap Factory Defective</b>
Distance (ft):	<b>168.1</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>TAP BROKEN. SERVICE ANGLED. SOIL VISIBLE AT THE SERVICE TO MAIN C</b>

---




Code:	<b>FM</b>
Description:	<b>Fracture Multiple</b>
Distance (ft):	<b>173.3</b>
Structural Grade:	<b>4</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>2</b>
Clock To:	<b>4</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	

---



Code:	<b>SZ</b>
Description:	<b>Surface Damage Other</b>
Distance (ft):	<b>183.5</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>3</b>
Clock To:	<b>5</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>A PIECE CHIPPED AWAY FROM THE JOINT.</b>

---



Code:	<b>FM</b>
Description:	<b>Fracture Multiple</b>
Distance (ft):	<b>191.8</b>
Structural Grade:	<b>4</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>7</b>
Clock To:	<b>4</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	<b>S03</b>
Within 8" of Joint:	<b>YES</b>
Remarks:	


---



Code: **SZ**  
Description: **Surface Damage Other**

Distance (ft): **218.8**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **A PIECE CHIPPED AWAY FROM THE JOINT.**

---



Code: **TF**  
Description: **Tap Factory**

Distance (ft): **224.1**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To:  
1st Value: **6.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **TF**  
 Description: **Tap Factory**

Distance (ft): **255.2**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TBD**  
 Description: **Tap Break-in/Hammer Defective**

Distance (ft): **297.1**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **SOIL VISIBLE AROUND THE SERVICE TO MAIN CONNECTION .**




Code:	<b>TBD</b>
Description:	<b>Tap Break-in/Hammer Defective</b>
Distance (ft):	<b>298.5</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>SOIL VISIBLE AROUND THE SERVICE TO MAIN CONNECTION .</b>

---



Code:	<b>TFD</b>
Description:	<b>Tap Factory Defective</b>
Distance (ft):	<b>301.0</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>2</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>SOIL VISIBLE IN THE SERVICE.</b>

---




Code: **TFD**  
 Description: **Tap Factory Defective**

Distance (ft): **317.4**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **100% PLUGGED WITH ROOTS.**



Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **318.5**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **326.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAR**  
 Description: **Deposits Attached Ragging**


Distance (ft): **334.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **JAL**  
 Description: **Joint Angular Large**

Distance (ft): **347.4**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:


---



Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **347.4**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **RFJ**  
Description: **Roots Fine Joint**

Distance (ft): **353.3**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **8**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S04**  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **JAM**  
Description: **Joint Angular Medium**


Distance (ft): **353.3**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **TF**  
Description: **Tap Factory**

Distance (ft): **354.4**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value: **6.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **ROOTS GROWING FROM THE SERVICE TO MAIN CONNECTION.**



Code: **TBI**  
Description: **Tap Break-in Intruding**

Distance (ft): **357.2**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **1**  
Clock To:  
1st Value: **6.000**  
2nd Value: **1.000**  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **SERVICE BROKEN. SOIL VISIBLE AT THE SERVICE TO MAIN CONNECTION.**



Code: **LL**  
 Description: **Line Left**

Distance (ft): **362.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **JAM**  
 Description: **Joint Angular Medium**

Distance (ft): **372.0**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **LR**  
 Description: **Line Right**

Distance (ft): **375.6**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **SZ**  
 Description: **Surface Damage Other**

Distance (ft): **382.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **A PIECE CHIPPED AWAY FROM THE JOINT.**




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **394.0**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F03**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **394.0**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F04**  
 Within 8" of Joint: **YES**  
 Remarks:



Code:	<b>AMH</b>
Description:	<b>Manhole</b>
Distance (ft):	<b>396.6</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	<b>M-805-055</b>