


# Profile/Photo Observation Report



Date:	<b>01/24/2023</b>	Weather:		Coding:	<b>PACP 7.0</b>
Pipe Length (ft):	<b>197.0</b>	Owner:	<b>City of Hobart</b>	Pre Clean:	<b>Heavy Cleaning</b>
P.O.#:	<b>YES502259</b>	Surveyor:	<b>Steven Bucklin</b>	PSR:	<b>P-805-059-058</b>
Customer:	<b>City of Hobart</b>	Clean Date:	<b>01/20/2023</b>	Shape:	<b>C</b>

Street:	<b>Devanshire Street</b>	Flow Control:	<b>Not Controlled</b>
City:	<b>Hobart, IN</b>	Year Renewed:	
Location:	<b>Local rural streets with light traffic, t</b>	Tape/Media #:	
Purpose:	<b>Routine Assessment</b>	Dia/Height:	<b>12"</b>
Use:	<b>Sanitary Sewage Pipe</b>	Material:	<b>VCP</b>
Drain Area:		Lining:	<b>None</b>
Category:	<b>NA</b>		
Comment:			
Location Details:		Direction of Survey:	<b>Downstream</b>
US MH:	<b>M-805-059</b>	DS MH:	<b>M-805-058</b>
		Total Length Surveyed (ft):	<b>193.9</b>

O&M Index:	<b>1.42</b>	O&M Quick:	<b>3824</b>	O&M Rating:	<b>68.00</b>
Structural Index:	<b>2.90</b>	Structural Quick:	<b>514A</b>	Structural Rating:	<b>122.00</b>
Overall Index:	<b>2.11</b>	Overall Quick:	<b>514A</b>	Overall Rating:	<b>190.00</b>


Position	Code	Observation	Video (sec)	Grade
				
.0	AMH	Manhole	1	NA
.0	MWL	Miscellaneous Water Level	62	NA
2.5	RMJ	Roots Medium Joint	128	M 3
4.3	MWLS(S01)	Miscellaneous Water Level Sag	153	S 2
8.6	JAL	Joint Angular Large	208	S 4
9.4	TBI	Tap Break-in Intruding	261	M 2
9.4	RTC	Roots Tap Connection	291	M 2
12.1	MWLS(F01)	Miscellaneous Water Level Sag	319	S 2
12.8	RFJ	Roots Fine Joint	371	M 1
12.8	ISGT	Intruding Sealing Material Grout	397	M 2
14.9	RMJ	Roots Medium Joint	458	M 3
17.0	RFJ	Roots Fine Joint	495	M 1
17.0	CM	Crack Multiple	523	S 3
19.1	JAM	Joint Angular Medium	552	S 3
23.5	SSS	Surface Damage Surface Spalling	590	S 2
27.2	RFJ(S02)	Roots Fine Joint	658	M 1
27.2	CL	Crack Longitudinal	683	S 2
28.4	TF	Tap Factory	713	NA
28.4	RMC	Roots Medium Connection	736	M 3

32.8	MWLS(S03)	Miscellaneous Water Level Sag	776	S 2
35.6	JAL	Joint Angular Large	843	S 4
35.6	B	Broken	850	S 4
35.6	CM	Crack Multiple	860	S 3
42.1	MWLS(F03)	Miscellaneous Water Level Sag	903	S 2
43.2	MWLS(S04)	Miscellaneous Water Level Sag	919	S 2
44.4	TFD	Tap Factory Defective	953	M 3
44.4	RML	Roots Medium Lateral	986	M 3
51.8	JAM	Joint Angular Medium	1109	S 3
51.8	CM	Crack Multiple	1124	S 3
55.4	JAM	Joint Angular Medium	1203	S 3
55.5	FM	Fracture Multiple	1210	S 4
61.7	JAL	Joint Angular Large	1304	S 4
61.7	FM	Fracture Multiple	1319	S 4
64.0	FM	Fracture Multiple	1367	S 4
64.0	JAM	Joint Angular Medium	1376	S 3
65.8	FM	Fracture Multiple	1427	S 4
66.1	MWLS(F04)	Miscellaneous Water Level Sag	1446	S 2
70.1	MWLS(S05)	Miscellaneous Water Level Sag	1469	S 2
79.8	MWLS(F05)	Miscellaneous Water Level Sag	1510	S 2
79.8	LL	Line Left	1517	M 1
86.7	JAL	Joint Angular Large	1590	S 4
86.7	FM	Fracture Multiple	1607	S 4
110.7	TFD	Tap Factory Defective	1704	M 3
115.6	JAM	Joint Angular Medium	1776	S 3
119.6	DAR	Deposits Attached Ragging	1812	M 2
122.8	TFD	Tap Factory Defective	1843	M 3
125.1	TF	Tap Factory	1898	NA
133.8	MWLS(S06)	Miscellaneous Water Level Sag	1944	S 2
139.8	MWLS(F06)	Miscellaneous Water Level Sag	1972	S 2
142.5	CM	Crack Multiple	2062	S 3
142.5	SZ	Surface Damage Other	2074	NA
156.4	MWLS(S07)	Miscellaneous Water Level Sag	2134	S 2
165.1	FM	Fracture Multiple	2201	S 4
167.2	RMJ	Roots Medium Joint	2242	M 3
177.1	MWLS(F07)	Miscellaneous Water Level Sag	2299	S 2
180.0	JAM	Joint Angular Medium	2350	S 3
184.0	JAM	Joint Angular Medium	2414	S 3
192.0	BVV	Broken Void Visible	2524	S 5
192.0	DR	Deformed Rigid	2549	S 4
193.5	RFJ(F02)	Roots Fine Joint	2571	M 1
193.9	AMH	Manhole	2703	NA



Code: **AMH**  
Description: **Manhole**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-805-059**




Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:



Code: **RMJ**  
 Description: **Roots Medium Joint**


Distance (ft): **2.5**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **4.3**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **20.000**  
 Continuous Index: **S01**  
 Within 8" of Joint: **NO**  
 Remarks:





Code: **JAL**  
 Description: **Joint Angular Large**

Distance (ft): **8.6**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **9.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **ROOTS GROWING IN THE SERVICE AND FROM THE SERVICE TO MAIN C**




Code: **RTC**  
 Description: **Roots Tap Connection**

Distance (ft): **9.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **10**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent: **20.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **12.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **20.000**  
 Continuous Index: **F01**  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **RFJ**  
Description: **Roots Fine Joint**


Distance (ft): **12.8**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **10**  
Clock To: **2**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:



Code: **ISGT**  
Description: **Intruding Sealing Material Grout**

Distance (ft): **12.8**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **4**  
Clock To: **8**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:






Code: **RMJ**  
 Description: **Roots Medium Joint**

Distance (ft): **14.9**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **17.0**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---



Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **17.0**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **JAM**  
 Description: **Joint Angular Medium**

Distance (ft): **19.1**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:






Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **23.5**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:


---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **27.2**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S02**  
 Within 8" of Joint: **YES**  
 Remarks:

---




Code: **CL**  
 Description: **Crack Longitudinal**

Distance (ft): **27.2**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **TF**  
 Description: **Tap Factory**

Distance (ft): **28.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **ROOTS GROWING FROM THE  
SERVICE TO MAIN CONNECTION INT**




Code:	<b>RMC</b>
Description:	<b>Roots Medium Connection</b>
Distance (ft):	<b>28.4</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>5.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	



Code:	<b>MWLS</b>
Description:	<b>Miscellaneous Water Level Sag</b>
Distance (ft):	<b>32.8</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>15.000</b>
Continuous Index:	<b>S03</b>
Within 8" of Joint:	<b>NO</b>
Remarks:	






Code: **JAL**  
Description: **Joint Angular Large**

Distance (ft): **35.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **B**  
Description: **Broken**

Distance (ft): **35.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **35.6**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**


Distance (ft): **42.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **15.000**  
 Continuous Index: **F03**  
 Within 8" of Joint: **NO**  
 Remarks:






Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **43.2**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **15.000**  
 Continuous Index: **S04**  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **TFD**  
 Description: **Tap Factory Defective**

Distance (ft): **44.4**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **99% PLUGGED WITH ROOTS.  
 CONSTANTLY RUNNING WATER.**




Code: **RML**  
 Description: **Roots Medium Lateral**

Distance (ft): **44.4**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **10**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **JAM**  
 Description: **Joint Angular Medium**


Distance (ft): **51.8**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **51.8**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **JAM**  
Description: **Joint Angular Medium**

Distance (ft): **55.4**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---






Code: **FM**  
Description: **Fracture Multiple**

Distance (ft): **55.5**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **9**  
Clock To: **11**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **JAL**  
Description: **Joint Angular Large**


Distance (ft): **61.7**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **FM**  
 Description: **Fracture Multiple**


Distance (ft): **61.7**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **FM**  
 Description: **Fracture Multiple**


Distance (ft): **64.0**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **JAM**  
 Description: **Joint Angular Medium**

Distance (ft): **64.0**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **65.8**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **66.1**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **F04**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **70.1**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **S05**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **79.8**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **F05**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **LL**  
Description: **Line Left**

Distance (ft): **79.8**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---






Code: **JAL**  
 Description: **Joint Angular Large**

Distance (ft): **86.7**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **86.7**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code:	<b>TFD</b>
Description:	<b>Tap Factory Defective</b>
Distance (ft):	<b>110.7</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>TAP BROKEN. SERVICE LARGE OFFSET. SOIL VISIBLE. ROOTS GROW</b>

---



Code:	<b>JAM</b>
Description:	<b>Joint Angular Medium</b>
Distance (ft):	<b>115.6</b>
Structural Grade:	<b>3</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	


---



Code: **DAR**  
Description: **Deposits Attached Ragging**

Distance (ft): **119.6**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **6**  
Clock To: **7**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **TFD**  
Description: **Tap Factory Defective**

Distance (ft): **122.8**  
Structural Grade: **0**  
O&M Grade: **3**  
Clock Start/From: **11**  
Clock To:  
1st Value: **6.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **CAPPED. CAP BROKEN. ROOTS GROWING AROUND THE CAP.**


---






Code:	<b>TF</b>
Description:	<b>Tap Factory</b>
Distance (ft):	<b>125.1</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>ROOTS GROWING FROM THE SERVICE TO MAIN CONNECTION INT</b>

---



Code:	<b>MWLS</b>
Description:	<b>Miscellaneous Water Level Sag</b>
Distance (ft):	<b>133.8</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>15.000</b>
Continuous Index:	<b>S06</b>
Within 8" of Joint:	<b>NO</b>
Remarks:	


---



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **139.8**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **F06**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **142.5**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **SZ**  
Description: **Surface Damage Other**

Distance (ft): **142.5**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **4**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **A PIECE CHIPPED AWAY FROM THE JOINT.**

---



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **156.4**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **20.000**  
Continuous Index: **S07**  
Within 8" of Joint: **NO**  
Remarks:

---






Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **165.1**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RMJ**  
 Description: **Roots Medium Joint**


Distance (ft): **167.2**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **177.1**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **20.000**  
Continuous Index: **F07**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **JAM**  
Description: **Joint Angular Medium**

Distance (ft): **180.0**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **JAM**  
 Description: **Joint Angular Medium**

Distance (ft): **184.0**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:

---




Code: **BVV**  
 Description: **Broken Void Visible**

Distance (ft): **192.0**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---






Code: **DR**  
 Description: **Deformed Rigid**

Distance (ft): **192.0**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:

---



Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **193.5**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F02**  
 Within 8" of Joint: **YES**  
 Remarks:

---



Code:	AMH
Description:	Manhole
Distance (ft):	193.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-805-058