Profile/Photo Observation Report



Date: 04/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 137.6 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-806-006-027 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: LUTHER DR & E 8TH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: may be 12" pipe.

Location Details: Direction of Survey: **Upstream**

US MH: M-806-006 DS MH: M-806-027 Total Length Surveyed (ft): 12.3

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
1(806-)027				
.0	AMH	Manhole	10	NA
0.0	MWL	Water Level	21	NA
3.0	TBI	Tap Break-in Intruding	39	M 2
/12.3	MSA	Abandoned Survey	70	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-027

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 4

Continuous Index:

Within 8" of Joint:

Remarks:

40.000

NO

Code: **TBI**

Description: Tap Break-in Intruding



Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3


Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 12.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: unknown