

## Profile/Photo Observation Report



Date:	<b>04/17/2018</b>	Weather:		Coding:	<b>PACP 6.0</b>
Pipe Length (ft):	<b>208.9</b>	Owner:	<b>NA</b>	Pre Clean:	<b>Not Known</b>
P.O.#:		Surveyor:	<b>Byrd Fitzgerald</b>	PSR:	<b>P-806-012-013</b>
Customer:		Clean Date:	<b>01/01/1900</b>	Shape:	<b>C</b>

Street:	<b>MEMORY LN</b>	Flow Control:	<b>Not Controlled</b>
City:	<b>Hobart, IN</b>	Year Renewed:	
Location:	<b>Ditch</b>	Tape/Media #:	
Purpose:	<b>Maintenance Related</b>	Dia/Height:	<b>10"</b>
Use:	<b>Sanitary</b>	Material:	<b>VCP</b>
Drain Area:	<b>NA</b>	Lining:	<b>Cured in Place</b>
Category:	<b>NA</b>		
Comment:	<b>heavy debris at 46'.</b>		

Location Details:		Direction of Survey:	<b>Upstream</b>
US MH:	<b>M-806-013</b>	DS MH:	<b>M-806-012</b>
		Total Length Surveyed (ft):	<b>47.2</b>

O&M Index:	<b>3.67</b>	O&M Quick:	<b>4231</b>	O&M Rating:	<b>11.00</b>
Structural Index:	<b>2.00</b>	Structural Quick:	<b>2100</b>	Structural Rating:	<b>2.00</b>
Overall Index:	<b>3.25</b>	Overall Quick:	<b>4231</b>	Overall Rating:	<b>13.00</b>

Position	Code	Observation	Video (sec)	Grade
M-806-012				
.0	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
5.5	MWLS	Water Level Sag	43	S 2
33.8	MCU	Camera Underwater	111	M 4
43.4	MCU(S01)	Camera Underwater	142	M 4
47.2	MSA	Abandoned Survey	161	NA
47.2	MCU(F01)	Camera Underwater	172	M 4
M-806-013				

Code: **AMH**  
Description: **Manhole**



---


Code:	<b>MWL</b>
Description:	<b>Water Level</b>



Distance (ft):	<b>.0</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>10.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	

---

Code:	<b>MWLS</b>
Description:	<b>Water Level Sag</b>



Distance (ft):	<b>5.5</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>3</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>10.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	

---

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **33.8**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---


Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **43.4**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S01**  
Within 8" of Joint: **NO**  
Remarks:

---


Code: **MSA**  
Description: **Abandoned Survey**



Distance (ft): **47.2**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **mcu**

---

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **47.2**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks: