


Profile/Ph	oto Observatior	n Report				RedZon
Date:	04/12/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 181.7	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello		PSR:	P-806-030-029
Customer:		Clean Date	: 01/01/1900		Shape:	с
Street:	E 8TH ST & 9TH CT	Г	Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewee	d:		
Location:	Sidewalk		Tape/Media #	!:		
Purpose:	Maintenance Rela	ited	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:	flow incorrect.					
Location Detail	ls:		Direction of S	urvey:	Downstream	
US MH:	M-806-029	DS MH:	M-806-030	Tot	al Length Surveyed (ft):	178.9
0&M Index:	0.00	O&M Quick	. C	000	O&M Rating:	0.00
tructural Index:	0.00	Structural Q	uick: C	000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quid	:k: C	000	Overall Rating:	0.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-029




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	157.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	161.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	178.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-030